

## Mask Set Errata for Mask 3M17W

### Introduction

This report applies to mask 3M17W for these products:

- MPC5674F

Errata ID	Errata Title
3521	DECFIL: Soft reset failures at the end of filtering
6026	DSPI: Incorrect SPI Frame Generated in Combined Serial Interface Configuration
818	EMIOS/ETPU: Global timebases not synchronized
3378	EQADC: Pull devices on differential pins may be enabled for a short period of time during and just after POR
5642	ETPU2: Limitations of forced instructions executed via the debug interface
6309	ETPU2: STAC bus timebase export to peripherals does not work if the ratio of eTPU clock to peripheral clock is 2:1.
2740	ETPU2: Watchdog Status Register (WDSR) may fail to update on channel timeout
5640	ETPU2: Watchdog timeout may fail in busy length mode
2382	FLASH: Flash Array Integrity Check
1312	FLASH: MCR[DONE] bit may be set before high voltage operation completes when executing a suspend sequence
3659	FLASH: Resuming after a suspend during an Erase may prevent the erase from completing.
3407	FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1
2424	FlexCAN: switching CAN protocol interface (CPI) to system clock has very small chance of causing the CPI to enter an indeterminate state
1364	FlexRay : Message Buffer Slot Status corrupted after system memory access timeout or illegal address access
1369	FlexRay : Message Buffer Status, Slot Status, and Data not updated after system memory access timeout or illegal address access
2302	FlexRay: Message Buffer can not be disabled and not locked after CHI command FREEZE
6726	NPC: MCKO clock may be gated one clock period early when MCKO frequency is programmed as SYS_CLK/8.and gating is enabled

*Table continues on the next page...*

Errata ID	Errata Title
3553	NXFR: Flexray databus translates into unexpected data format on the Nexus interface
1279	NZ7C3:Core Nexus Read/Write Access registers cleared by system reset
7120	NZxC3: DQTAG implemented as variable length field in DQM message
2696	PBRIDGE: Write buffer may cause overflow/underflow of DMA transfers
2996	PIT_RTI: RTI timer corruption when debugging
2322	PMC: LVREH/LVREA/LVRE50 may exit LVI triggered reset with LVI condition still existing
3377	Pad Ring:Nexus pins may drive an unknown value immediately after power up but before the 1st clock edge
1419	SIU: Reverting ENGCLK source to the system clock has a very small chance of causing the ENGCLK generator to enter an indeterminate state
4396	e200z7: Erroneous Address Fetch
3419	e200z: Exceptions generated on speculative prefetch
6966	eDMA: Possible misbehavior of a preempted channel when using continuous link mode
4480	eQADC: Differential conversions with 4x gain may halt command processing
5086	eQADC: unexpected result may be pushed when Immediate Conversion Command is enabled
2386	eSCI : No LIN frame reception after leaving stop mode
1171	eSCI : DMA stalled after return from stop or doze mode
2396	eSCI : Stop Mode not entered in LIN mode
1297	eSCI : reads of the SCI Data Register, which clears the RDRF flag, may cause loss of frame if read occurs during reception of the STOP bit
1381	eSCI: LIN Wakeup flag set after aborted LIN frame transmission
1221	eSCI: LIN bit error indicated at start of transmission after LIN reset

### e3521: DECFIL: Soft reset failures at the end of filtering

**Errata type:** Errata

**Description:** If a software reset of a decimation filter is made exactly at the time it finishes filtering, several registers reset for one clock, but have their values updated by the filtering on the next clock, including (but not limited to) the integrator current value register DECFIL\_CINTVAL and the tap registers DECFILTER\_TAPn.

**Workaround:** Before making the soft reset write (DECFIL\_MCR bit SRES=1), perform the procedure below:

- 1- disable filter inputs, writing DECFIL\_MCR bit IDIS = 1.
- 2- read the register DECFIL\_MSR and repeat the read until the bit BSY is 0.
- 3- repeat the loop of step 2; this is necessary to cover the case when a sample is left in the input buffer.

### e6026: DSPI: Incorrect SPI Frame Generated in Combined Serial Interface Configuration

**Errata type:** Errata

**Description:** In the Combined Serial Interface (CSI) configuration of the Deserial Serial Peripheral Interface (DSPI) where data frames are periodically being sent (Deserial Serial Interface, DSI), a Serial Peripheral Interface (SPI) frame may be transmitted with incorrect framing.

The incorrect frame may occur in this configuration if the user application writes SPI data to the DSPI Push TX FIFO Register (DSPI\_PUSHR) during the last two peripheral clock cycles of the Delay-after-Transfer (DT) phase. In this case, the SPI frame is corrupted.

**Workaround:** Workaround 1: Perform SPI FIFO writes after halting the DSPI.

To prevent writing to the FIFO during the last two clock cycles of DT, perform the following steps every time a SPI frame is required to be transmitted:

Step 1: Halt the DSPI by setting the HALT control bit in the Module Configuration Register (DSPI\_MCR[HALT]).

Step 2: Poll the Status Register's Transmit and Receive Status bit (DSPI\_SR[TXRXS]) to ensure the DSPI has entered the HALT state and completed any in-progress transmission. Alternatively, if continuous polling is undesirable in the application, wait for a fixed time interval such as 35 baud clocks to ensure completion of any in-progress transmission and then check once for DSPI\_SR[TXRXS].

Step 3: Perform the write to DSPI\_PUSHR for the SPI frame.

Step 4: Clear bit DSPI\_MCR[HALT] to bring the DSPI out of the HALT state and return to normal operation.

Workaround 2: Do not use the CSI configuration. Use the DSPI in either DSI-only mode or SPI-only mode.

Workaround 3: Use the DSPI's Transfer Complete Flag (TCF) interrupt to reduce worst-case wait time of Workaround 1.

Step 1: When a SPI frame is required to be sent, halt the DSPI as in Step 1 of Workaround 1 above.

Step 2: Enable the TCF interrupt by setting the DSPI DMA/Interrupt Request Select and Enable Register's Transmission Complete Request Enable bit (DSPI\_RSER[TCF\_RE]).

Step 3: In the TCF interrupt service routine, clear the interrupt status (DSPI\_SR[TCF]) and the interrupt request enable (DSPI\_RSER[TCF\_RE]). Confirm that DSPI is halted by checking DSPI\_SR[TXRXS] and then write data to DSPI\_PUSHR for the SPI frame. Finally, clear bit DSPI\_MCR[HALT] to bring the DSPI out of the HALT state and return to normal operation.

## **e818: EMIOS/ETPU: Global timebases not synchronized**

**Errata type:** Errata

**Description:** The eTPU and eMIOS timebases can be started synchronously by asserting the Global Time Base Enable (GTBE) bit in either the eTPU Module Configuration Register (eTPUMCR) or the eMIOS Module Configuration Register (eMIOS\_MCR). GTBE bits from the eMIOS and eTPU are ORed together such that asserting either of them allows both eMIOS and eTPU timebases to start running simultaneously.

When the timebases are running and GTBE is cleared, the timebase and eTPU Angle Counter (EAC) prescalers can stop at any count. When GTBE is reasserted, the prescalers must have a determined initialization value so that the timebases will remain in sync with each other.

**Workaround:** Perform the following steps in sequence to synchronize the time base between the eTPU and the eMIOS:

- 1- Clear the Global Time Base Enable (GTBE) bit in the eTPU Module Configuration Register (ETPUMCR[GTBE] = 0).
- 2- Clear the Global Time Base Enable (GTBE) and Global Prescaler Enable (GPREN) bits in the eMIOS Module Configuration Register (EMIOS\_MCR[GTBE] = 0, EMIOS\_MCR[GPREN] = 0) to stop the Global Clock Prescaler (GCP) from counting.
- 3- Write the desired counter values to the eTPU Time Counter Registers 1 and 2 (TCR1 and TCR2) with eTPU microcode (these registers cannot be written by the CPU). This step is required even if the values in TCR1 and TCR2 are not changed.
- 4- Clear the Unified Channel Prescaler Enable (UCPREN) bit in the eMIOS Channel Control Register (EMIOS\_CCRn) for each of the eMIOS channels (EMIOS\_CCRn[UCPREN] = 0).
- 5- If it is necessary to set the eMIOS counters to known values, configure each eMIOS channel for General Purpose Input (GPI) mode (EMIOS\_CCRn[MODE] = 0000000), write the desired counter values, and restore the desired operational mode (EMIOS\_CCRn[MODE] = xxxxxxx).
- 6- Set the UCPREN bit in the EMIOS\_CCRn register for each of the eMIOS channels (EMIOS\_CCRn[UCPREN] = 1) to re-enable the unified channel prescaler.
- 7- Set the GTBE and GPREN bits in the eMIOS MCR simultaneously with a single write operation (EMIOS\_MCR = EMIOS\_MCR | 0x14000000).

Note: This works only for eTPU and single eMIOS module synchronization. For more than one eMIOS module there is no workaround, since their GPREN bits cannot be written at the same time.

### **e3378: EQADC: Pull devices on differential pins may be enabled for a short period of time during and just after POR**

**Errata type:** Errata

**Description:** The programmable pull devices (up and down) on the analog differential inputs of the eQADC may randomly be enabled during the internal Power On Reset (POR) and until the 1st clock edge propagates through the device. After the first clock edge, the pull resistors will be disabled until software enables them.

**Workaround:** Protect any external devices connected to the differential analog inputs. The worst case condition is with a 1.4K ohm resistor to VDDA (5K pull-up enabled) or VSSA (5K pull-down enabled). This may also cause temporary additional current requirements on the VDDA supply of each eQADC module, up to 15 mA on each eQADC if both the pull up and pull down resistors are enabled simultaneously on all of the differential analog pins.

### **e5642: ETPU2: Limitations of forced instructions executed via the debug interface**

**Errata type:** Information

**Description:** The following limitations apply to forced instructions executed through the Nexus debug interface on the Enhanced Time Processing Unit (ETPU):

- 1- When a branch or dispatch call instruction with the pipeline flush enabled (field FLS=0) is forced (through the debug port), the Return Address Register (RAR) is updated with the current program counter (PC) value, instead of PC value + 1.
- 2- The Channel Interrupt and Data Transfer Requests (CIRC) instruction field is not operational.

**Workaround:** Workaround for limitation #1 (branch or dispatch call instruction):

Increment the PC value stored in the RAR by executing a forced Arithmetic Logic Unit (ALU) instruction after the execution of the branch or dispatch call instruction.

Workaround for limitation #2 (CIRC):

To force an interrupt or DMA request from the debugger:

- 1- Program a Shared Code Memory (SCM) location with an instruction that issues the interrupt and/or DMA request. Note: Save the original value at the SCM location.
- 2- Save the address of the next instruction to be executed.
- 3- Force a jump with flush to the instruction position.
- 4- Single-step the execution.
- 5- Restore the saved value to the SCM location (saved in step 1).
- 6- Force a jump with flush to the address of the next instruction to be executed (saved in step 2).

NOTE: This workaround cannot be executed when the eTPU is in HALT\_IDLE state.

### **e6309: ETPU2: STAC bus timebase export to peripherals does not work if the ratio of eTPU clock to peripheral clock is 2:1.**

**Errata type:** Errata

**Description:** The Shared Time Angle Counter (STAC) bus allows an Enhanced Time Processing Unit (eTPU) to export its timebase or angle counters to another eTPU as well as to other peripherals such as the Enhanced Modular Input/Output Subsystem (eMIOS) and Enhanced Queued Analog-to-Digital Converter (eQADC). If the eTPU clock is configured to be twice the frequency of those peripherals, the STAC bus will not be able to transfer timebase or angle information from the eTPUs to the slower peripherals. The timebase/angle export between eTPUs, however, is still operational in this configuration.

**Workaround:** Configure the eTPU clock to the same frequency as peripherals if timebase/angle export to them is required.

### **e2740: ETPU2: Watchdog Status Register (WDSR) may fail to update on channel timeout**

**Errata type:** Errata

**Description:** The Watchdog Status Register (WDSR) contains a single watchdog status bit for each of the 32 eTPU channels per engine. When this bit is set, it indicates that the corresponding channel encountered a watchdog timeout and was aborted. Under certain conditions the corresponding bit is not set due to a watchdog timeout, and therefore no indication is available as to which channel timed out. However, the global exception is indicated correctly on a per engine basis, and the correct exception is issued to the interrupt controller and may be serviced.

**Workaround:** The application software should treat any watchdog event as a global eTPU exception and handle it in the eTPU global exception handler. Additionally, during the global exception handler the application should check the WDSR and clear any bits that may be set by writing '1' to that bit.

## **e5640: ETPU2: Watchdog timeout may fail in busy length mode**

**Errata type:** Errata

**Description:** When the Enhanced Time Processing Unit (eTPU) watchdog is programmed for busy length mode (eTPU Watchdog Timer Register (ETPU\_WDTR) Watchdog Mode field (WDM) = 3), a watchdog timeout will not be detected if all of the conditions below are met:

- 1- The watchdog timeout occurs at the time slot transition, at the first instruction of a thread, or at the thread gap. (a thread gap is a 1 microcycle period between threads that service the same channel).
- 2- The thread has only one instruction.
- 3- The eTPU goes idle right after the timed-out thread, or after consecutive single-instruction threads.

**Workaround:** Insert a NOP instruction in threads which have only one instruction.

## **e2382: FLASH: Flash Array Integrity Check**

**Errata type:** Errata

**Description:** The Flash Array Integrity Check (AIC) which may be enabled during the flash user test (UTest) mode does not return the expected UMn[MISR] values for some flash PFCRPn[RWSC] read wait state configurations. For PFCRPn[RWSC] values of 3-6, the UMn[MISR] signature computation during AIC does not include the data read from the very last address in the selected address sequence and thus the UMn[MISR] value is not as expected. For PFCRPn[RWSC] values of 7, the UMn[MISR] signature computation during AIC will not be correct as well.

**Workaround:** The Flash Array Integrity Check is correct for PFCRPn[RWSC] values of 0-2. For PFCRPn[RWSC] values of 3-6, the expected UMn[MISR] values will not include the data read from the very last address and thus the value expected should be for the data read up to the 2nd-last address in the selected address sequence. For a PFCRPn[RWSC] value of 7, the Array Integrity Check should not be used at all.

## **e1312: FLASH: MCR[DONE] bit may be set before high voltage operation completes when executing a suspend sequence**

**Errata type:** Errata

**Description:** The program and erase sequence of the flash may be suspended to allow read and program access to the flash core. A suspend operation is initiated by setting the Erase Suspend (ESUS) bit or Program Suspend (PSUS) bit in the flash Module Configuration Register (MCR). Setting a suspend bit causes the flash module to start the sequence which places it in the suspended state. The user must then wait until the MCR[DONE] bit is set before a read or program to the flash is initiated, as the high voltage operation needs to be complete to avoid errors.

However, during normal read to the same partition, following a suspend sequence, (setting MCR bit and waiting for MCR[DONE] bit to be set) can result in read fails that will return multiple bit ECC errors. The error is due to the MCR[DONE] bit being set before the internal high voltage operation is complete.

**Workaround:** Because the MCR[DONE] flag can be set too soon, a delay needs to be inserted between setting the MCR[ESUS] or MCR[PSUS] and reading the same flash partition. The minimum duration of the delay should be 40us to guarantee correct operation. The Freescale flash programming driver includes this workaround.

### **e3659: FLASH: Resuming after a suspend during an Erase may prevent the erase from completing.**

**Errata type:** Errata

**Description:** If an erase suspend (including the flash put into sleep or disabled mode) is done on any block in the low Address Space (LAS) or the Mid-Address Space (MAS) except the 16 KB blocks, or if a suspend is done with multiple non-adjacent blocks (including the High Address Space [HAS]), the flash state machine may not set the FLASH\_MCR[DONE] bit in the flash Module Control Register. This condition only occurs if the suspend occurs during certain internal flash erase operations. The likelihood of an issue occurring is reduced by limiting the frequency of suspending the erase operation.

**Workaround:** If the suspend feature (including disable and sleep modes) of the flash is used, then software should ensure that if the maximum time allowed for an erase operation occurs without a valid completion flag from the flash (FLASH\_MCR[DONE] = 1), the software should abort the erase operation (by first clearing the Enable High Voltage (FLASH\_MCR[EHV] ) bit, then clearing the Erase read/Write bit (FLASH\_MCR[ERS] bit) and the erase operation should be restarted.

Note: The cycle count of the sector is increased by this abort and restart operation.

### **e3407: FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1**

**Errata type:** Errata

**Description:** FlexCAN does not transmit an expected message when the same node detects an incoming Remote Request message asking for any remote answer.

The issue happens when two specific conditions occur:

- 1) The Message Buffer (MB) configured for remote answer (with code "a") is the last MB. The last MB is specified by Maximum MB field in the Module Configuration Register (MCR[MAXMB] ).
- 2) The incoming Remote Request message does not match its ID against the last MB ID.

While an incoming Remote Request message is being received, the FlexCAN also scans the transmit (Tx) MBs to select the one with the higher priority for the next bus arbitration. It is expected that by the Intermission field it ends up with a selected candidate (winner). The coincidence of conditions (1) and (2) above creates an internal corner case that cancels the Tx winner and therefore no message will be selected for transmission in the next frame. This gives the appearance that the FlexCAN transmitter is stalled or "stops transmitting".

The problem can be detectable only if the message traffic ceases and the CAN bus enters into Idle state after the described sequence of events.

There is NO ISSUE if any of the conditions below holds:

- a) The incoming message matches the remote answer MB with code "a".
- b) The MB configured as remote answer with code "a" is not the last one.

c) Any MB (despite of being Tx or Rx) is reconfigured (by writing its CS field) just after the Intermission field.

d) A new incoming message sent by any external node starts just after the Intermission field.

**Workaround:** Do not configure the last MB as a Remote Answer (with code "a").

#### **e2424: FlexCAN: switching CAN protocol interface (CPI) to system clock has very small chance of causing the CPI to enter an indeterminate state**

**Errata type:** Errata

**Description:** The reset value for the clock source of the CAN protocol interface (CPI) is the oscillator clock. If the CPI clock source is switched to the system clock while the FlexCAN is not in freeze mode, then the CPI has a very small chance of entering an indeterminate state.

**Workaround:** Switch the clock source while the FlexCAN is in a halted state by setting HALT bit in the FlexCAN Module Configuration Register (CANx\_MCR[HALT]=1). If the write to the CAN Control Register to change the clock source (CANx\_CR[CLK\_SRC]=1) is done in the same oscillator clock period as the write to CANx\_MCR[HALT], then chance of the CPI entering an indeterminate state is extremely small. If those writes are done on different oscillator clock periods, then the corruption is impossible. Even if the writes happen back-to-back, as long as the system clock to oscillator clock frequency ratio is less than three, then the writes will happen on different oscillator clock periods.

#### **e1364: FlexRay : Message Buffer Slot Status corrupted after system memory access timeout or illegal address access**

**Errata type:** Errata

**Description:** If the system memory read access that retrieves the first message buffer header data from a FlexRay transmit buffer fails due to a system memory access timeout or illegal address access, it is possible that the slot status information for the previous slot is written into the currently used transmit message buffer. In this case, the slot status information is not written into the message buffer assigned to the last slot.

Thus, both the message buffer assigned to the last slot, and the currently used transmit message buffer contain incorrect slot status information.

However, if this occurs, either the System Bus Communication Failure Error Flag (SBCF\_EF) or the Illegal System Bus Address Error Flag (ILSA\_EF) will be set in the Controller Host Interface Error Flag Register (CHIERFR).

**Workaround:** The FlexRay module and the system memory subsystem should be configured to avoid the occurrence of system memory access timeouts and illegal address accesses.

In case that one of the error flags CHIERFR[SBCF\_EF] or CHIERFR[ILSA\_EF] is set, the application should not use the slot status information of the message buffers.

#### **e1369: FlexRay : Message Buffer Status, Slot Status, and Data not updated after system memory access timeout or illegal address access**

**Errata type:** Errata

**Description:** If a message buffer is assigned to the last slot in a FlexyRay communication cycle and a system memory access timeout or illegal address access occurs during the system memory access in this slot, it is possible that for all future communication 1) no slot status information will be written, 2) the message buffer status will not be updated, and 3) no message frames will be received. If this happens, several message buffers can never be locked by the application.

However, if this occurs, either the System Bus Communication Failure Error Flag (SBCF\_EF) or the Illegal System Bus Address Error Flag (ILSA\_EF) will be set in the Controller Host Interface Error Flag Register (CHIERFR).

**Workaround:** The FlexRay module and the system memory subsystem should be configured to avoid the occurrence of system memory access timeouts and illegal address accesses.

In case that one of the error flags CHIERFR[SBCF\_EF] or CHIERFR[ILSA\_EF] is set, the application should stop the FlexRay controller via a FREEZE or HALT command and subsequently restart the controller.

### **e2302: FlexRay: Message Buffer can not be disabled and not locked after CHI command FREEZE**

**Errata type:** Errata

**Description:** If a complete message was transmitted from a transmit message buffer or received into a message buffer and the controller host interface (CHI) command FREEZE is issued by the application before the end of the current slot, then this message buffer can not be disabled and locked until the module has entered the protocol state normal active.

Consequently, this message buffer can not be disabled and locked by the application in the protocol config state, which prevents the application from clearing the commit bit CMT and the module from clearing the status bits. The configuration bits in the Message Buffer Configuration, Control, Status Registers (MBCCSRn) and the message buffer configuration registers MBCCFRn, MBFIDRn, and MBIDXRn are not affected.

At most one message buffer per channel is affected.

**Workaround:** There are two types of workaround.

1) The application should not send the CHI command FREEZE and use the CHI command HALT instead.

2) Before sending the CHI command FREEZE the application should repeatedly try to disable all message buffers until all message buffers are disabled. This maximum duration of this task is three static or three dynamic slots.

### **e6726: NPC: MCKO clock may be gated one clock period early when MCKO frequency is programmed as SYS\_CLK/8 and gating is enabled**

**Errata type:** Errata

**Description:** The Nexus auxiliary message clock (MCKO) may be gated one clock period early when the MCKO frequency is programmed as SYS\_CLK/8 in the Nexus Port Controller Port Configuration Register (NPC\_PCR[MCKO\_DIV]=111) and the MCKO gating function is enabled (NPC\_PCR[MCKO\_GT]=1). In this case, the last MCKO received by the tool prior to the gating will correspond to the END\_MESSAGE state. The tool will not receive an MCKO to indicate the transition to the IDLE state, even though the NPC will transition to the IDLE state internally. Upon re-enabling of MCKO, the first MCKO edge will drive the Message Start/End Output (MSEO=11) and move the tool's state to IDLE.

**Workaround:** Expect to receive the MCKO edge corresponding to the IDLE state upon re-enabling of MCKO after MCKO has been gated.

### **e3553: NXFR: Flexray databus translates into unexpected data format on the Nexus interface**

**Errata type:** Errata

**Description:** The data format for Nexus Flexray messages is in little-endian (least significant byte first) order. This is not currently documented and may be unexpected for users of Power Architecture devices.

For example, in the case of a Flexray System Memory write within the address space determined by Data Trace Start and Data Trace End Addresses (DTSAX/DTEAX) with the data: 0x1122, the Flexray Nexus interface generates Data Trace Messages (DTM) containing the data: 0x2211.

**Workaround:** The user must be aware of the data format. This will be documented in a future release of the device reference manual.

### **e1279: NZ7C3:Core Nexus Read/Write Access registers cleared by system reset**

**Errata type:** Errata

**Description:** The e200z7 Nexus Read/Write Access registers are cleared when system reset is asserted. This affects the Read/Write Access Data register (RWD), the Read/Write Access Address register (RWA), and the Read/write Access Control/Status register (RWCS).

**Workaround:** Do not expect RWD, RWCS, and RWA to retain values after reset. After reset reload any values required for a transfer.

### **e7120: NZxC3: DQTAG implemented as variable length field in DQM message**

**Errata type:** Errata

**Description:** The e200zx core implements the Data Tag (DQTAG) field of the Nexus Data Acquisition Message (DQM) as a variable length packet instead of an 8-bit fixed length packet. This may result in an extra clock ("beat") in the DQM trace message depending on the Nexus port width selected for the device.

**Workaround:** Tools should decode the DQTAG field as a variable length packet instead of a fixed length packet.

### **e2696: PBRIDGE: Write buffer may cause overflow/underflow of DMA transfers**

**Errata type:** Errata

**Description:** Peripheral-paced DMA transfers are controlled by a hardware handshake protocol: when the peripheral requires a data transfer, it asserts a request to the DMA. The DMA recognizes the request, activates the corresponding channel and performs the data transfer, reading from the source and writing to the destination. As the write is being processed, the DMA sends an acknowledge back to the peripheral so it can negate its request.

If buffered writes are enabled in the PBRIDGE, there are certain conditions where the DMA's acknowledge is asserted before the actual write operation to the peripheral has occurred. The net effect is the DMA request is not negated properly, causing the DMA to reactivate the channel, overwriting the last transferred data value before it is transferred to the peripheral.

**Workaround:** Do not enable buffered writes for the eDMA in the Peripheral Bridge Master Privilege Control registers (PBRIDGE\_A\_MPCR and PBRIDGE\_B\_MPCR), by leaving the MBW4 (eDMA A master) and MBW5 (eDMA B master) bits cleared. This is the default state of these bits, which disables buffered writes to the peripherals from both eDMA masters.

## **e2996: PIT\_RTI: RTI timer corruption when debugging**

**Errata type:** Errata

**Description:** In rare cases, due to a synchronization issue, the Real-Time Interrupt (RTI) timer value may become corrupted when a breakpoint occurs and the freeze bit is set to pause the timers in debug mode (PIT\_RTI\_MCR[FRZ]=0b1).

None of the other timers in the PIT\_RTI module are affected. During normal operation (without debugger attached) there is no impact to the application.

**Workaround:** When debugging code utilizing the RTI, do not depend on the value of the RTI timer being correct.

## **e2322: PMC: LVREH/LVREA/LVRE50 may exit LVI triggered reset with LVI condition still existing**

**Errata type:** Information

**Description:** After asserting the Low Voltage Reset Enables PMC\_CFGR[LVREH], PMC\_CFGR[LVREA], PMC\_CFGR[LVRE50] bits in the PMC, if the voltage ramps down below the LVI voltage on VDDEHx, VDDA or VDDREG respectively, the part will go to a short power on reset (POR). After the reset counter has expired, the device will go into normal operation, even though one or more of the affected supplies may still be below the specified LVI voltage.

**Workaround:** The part will recover into normal operation, however software should check the status of the LVIs for those segments that are required for further operation.

## **e3377: Pad Ring:Nexus pins may drive an unknown value immediately after power up but before the 1st clock edge**

**Errata type:** Errata

**Description:** The Nexus Output pins (Message Data outputs 0:15 [MDO] and Message Start/End outputs 0:1 [MSEO]) may drive an unknown value (high or low) immediately after power up but before the 1st clock edge propagates through the device (instead of being weakly pulled low). This may cause high currents if the pins are tied directly to a supply/ground or any low resistance driver (when used as a general purpose input [GPI] in the application).

**Workaround:** 1. Do not tie the Nexus output pins directly to ground or a power supply.

2. If these pins are used as GPI, limit the current to the ability of the regulator supply to guarantee correct start up of the power supply. Each pin may draw upwards of 150mA.

If not used, the pins may be left unconnected.

## **e1419: SIU: Reverting ENGCLK source to the system clock has a very small chance of causing the ENGCLK generator to enter an indeterminate state**

**Errata type:** Errata

**Description:** The reset value for the Engineering Clock (ENGCLK) source is the system clock. If the clock source is switched to the external clock (buffered crystal frequency or external clock input) by setting Engineering Clock Source Select bit in the External Clock Control Register (SIU\_ECCR[ECSS]=1) and then reverted to the system clock, then the ENGCLK generator has a very small chance of entering an indeterminate state.

**Workaround:** Do not change the ENGCLK source back to the System clock after changing it to the external clock.

## **e4396: e200z7: Erroneous Address Fetch**

**Errata type:** Errata

**Description:** Under certain conditions, if a static branch prediction and a dynamic return prediction (which uses the subroutine return address stack) occur simultaneously in the Branch Target Buffer (BTB), the e200z7 core can issue an errant fetch address to the memory system (instruction fetched from wrong address).

This can only happen when the static branch prediction is "taken" but the branch actually resolves to "not taken". If the branch resolves to taken, correct fetching occurs for this branch path and no issue is seen.

If Branch Unit Control and Status Register (BUCSR) Branch Prediction Control Static (BPRED) = 0b00, 0b01, or 0b10, then static branch prediction is configured as "taken". The issue can occur with these settings.

If BUSCR[BPRED] = 0b11, then static branch prediction is configured as "not taken". The issue does not occur with this setting.

**Workaround:** To prevent the issue from occurring, configure static branch prediction to "not taken" by setting the Branch Unit Control and Status Register (BUCSR) Branch Prediction Control Static (BPRED) to 0b11.

## **e3419: e200z: Exceptions generated on speculative prefetch**

**Errata type:** Errata

**Description:** The e200z7 core can prefetch up to 2 cache lines (64 bytes total) beyond the current instruction execution point. If a bus error occurs when reading any of these prefetch locations, the machine check exception will be taken. For example, executing code within the last 64 bytes of a memory region such as internal SRAM, may cause a bus error when the core pre-fetches past the end of memory. An ECC exception can occur if the core prefetches locations that are valid, but not yet initialized for ECC.

The Boot Assist Monitor (BAM) is located at the end of the address space and so may cause instruction pre-fetches to wrap-around to address 0 in internal flash memory. If this first block of flash memory contains ECC errors, such as from an aborted program or erase operation, a machine-check exception will be asserted. At this point in the boot procedure, exceptions are disabled, but the machine-check will remain pending and the exception vector will be taken if user application code subsequently enables the machine check interrupt.

**Workaround:** Do not place code to be executed within the last 64 bytes of a memory region. When executing code from internal ECC SRAM, initialize memory beyond the end of the code until the next 32-byte aligned address and then an additional 64 bytes to ensure that prefetches cannot land in uninitialized SRAM.

To guard against the possibility of the BAM causing a machine-check exception to be taken, as noted in the errata description, user application code should check and clear the Machine Check Syndrome Register (MCSR) in the core before enabling the machine check interrupt. This can be done by writing all 1s to MCSR.

## **e6966: eDMA: Possible misbehavior of a preempted channel when using continuous link mode**

**Errata type:** Errata

**Description:** When using Direct Memory Access (DMA) continuous link mode Control Register Continuous Link Mode (DMA\_CR[CLM]) = 1 with a high priority channel linking to itself, if the high priority channel preempts a lower priority channel on the cycle before its last read/write sequence, the counters for the preempted channel (the lower priority channel) are corrupted. When the preempted channel is restored, it continues to transfer data past its "done" point (that is the byte transfer counter wraps past zero and it transfers more data than indicated by the byte transfer count (NBYTES)) instead of performing a single read/write sequence and retiring.

The preempting channel (the higher priority channel) will execute as expected.

**Workaround:** Disable continuous link mode (DMA\_CR[CLM]=0) if a high priority channel is using minor loop channel linking to itself and preemption is enabled. The second activation of the preempting channel will experience the normal startup latency (one read/write sequence + startup) instead of the shortened latency (startup only) provided by continuous link mode.

## **e4480: eQADC: Differential conversions with 4x gain may halt command processing**

**Errata type:** Errata

**Description:** If the four times amplifier is enabled for a differential analog-to-digital conversion in the Enhanced Queued Analog to Digital Converter (eQADC) and the ADC clock prescaler is set to divide by 12 or greater, then the ADC will stop processing commands if a conversion command is executed immediately after a differential, gain 4x conversion.

**Workaround:** 1) Do not use a prescaler divide factor greater than or equal to 12 (11 can be used on devices that support odd prescalers).

2) Insert a dummy write command to any internal ADC register after every 4x conversion command.

Note 1: If the command FIFO preemption feature is used and it is possible to preempt a FIFO which contains the 4x conversion + dummy write workaround, then the preempting command FIFO must be loaded FIRST with a dummy write command and then the desired preempting conversion command in order to avoid the possibility of following a 4x conversion command with another conversion command in the same ADC.

Note 2: The level sensitive triggers (when in Low/High Level Gated External Trigger, Single/Continuous Scan modes) can interrupt the command sequence at any point in time, potentially breaking the safe sequence 4x conversion command -> dummy write command.

Note 3: When using an odd prescaler ( $ADCx\_CLK\_ODD = 1$ ), the duty cycle setting ( $ADCxCLK\_DTY$ ) must be kept at the default setting of 0.

### **e5086: eQADC: unexpected result may be pushed when Immediate Conversion Command is enabled**

**Errata type:** Errata

**Description:** In the enhanced Queued Analog to Digital Converter (eQADC), when the Immediate Conversion Command is enabled ( $ICEAn=1$ ) in the eQADC\_MCR (Module Configuration Register), if a conversion from Command First-In-First Out (CFIFO0, conv0) is requested concurrently with the end-of-conversion from another, lower priority conversion (convx), the result of the convx may be lost or duplicated causing an unexpected number of results in the FIFO (too few or too many).

**Workaround:** Workaround 1: Do not use the abort feature ( $ICEAn=0$ ).

Workaround 2: Arrange the timing of the CFIFO0 trigger such that it does not assert the trigger at the end of another, lower priority conversion.

Workaround 3: Detect the extra or missing conversion result by checking the EQADC\_CFTCRx (EQADC CFIFO Transfer Counter Register x). This register records how many commands were issued, so it can be used to check that the expected number of results have been received.

### **e2386: eSCI : No LIN frame reception after leaving stop mode**

**Errata type:** Errata

**Description:** When the eSCI module is in LIN mode and transmits or receives an LIN frame, if the CPU requests Stop Mode, and the Stop Mode is left, an subsequent triggered LIN RX Frame reception may hang. The module will never assert the eSCI\_IFSR2[RXRDY] and eSCI\_IFSR2[TXRDY] flags.

**Workaround:** The application should ensure that no LIN transmission is running before it requests Stop Mode by checking the status of the eSCI\_IFSR1[TACT] and eSCI\_IFSR1[RACT] status flags.

### **e1171: eSCI : DMA stalled after return from stop or doze mode**

**Errata type:** Errata

**Description:** If the eSCI module enters stop or doze mode while the transmit DMA is enabled and messages are being transmitted, when the CPU exits stop or doze mode, it is possible that DMA requests will not be generated by the eSCI module.

**Workaround:** The application should ensure that the eSCI module is idle before entering the stop mode.

The eSCI module is idle when both transmitter and receiver active status bits in the Interrupt Flag and Status Register 1 (eSCI\_IFSR1) are not set.

The application should not trigger a new transmission on the eSCI module if the application is preparing for the stop mode.

## **e2396: eSCI : Stop Mode not entered in LIN mode**

**Errata type:** Errata

**Description:** When the eSCI module is in LIN mode and transmits the Header of an LIN RX frame, if the CPU requests Stop Mode, the eSCI module may not acknowledge the Stop Mode request and will stay in Normal Operating Mode (not in lower power stop mode).

**Workaround:** The application should ensure that no LIN transmission is running before it requests Stop Mode by checking the Transmit Active and Receive Active status bits in the eSCI Interrupt Flag and Status Register (eSCI\_IFSR1[TACT] and eSCI\_IFSR1[RACT]).

## **e1297: eSCI : reads of the SCI Data Register, which clears the RDRF flag, may cause loss of frame if read occurs during reception of the STOP bit**

**Errata type:** Errata

**Description:** A received SCI frame is not written into the SCI Data Registers and the Overrun (OR) flag is not set in the SCI Status Register 1 (SCISR1), if:

- 1.) The eSCI has received the last data bit of an SCI frame n
- 2.) and the Receive Data Register Full (RDRF) flag is still set in the SCISR1 after the reception of SCI frame n-1
- 3.) and during the reception of the STOP bit of frame n the host reads the SCI Data Registers, and clears the RDRF flag

In this case the RDRF flag is erroneously set again by the controller instead of the OR flag. Thus, the host reads the data of frame n-1 a second time, and the data of frame n is lost.

**Workaround:** The application should ensure that the data of the foregoing frame is read out from the SCI Data Registers before the last data bit of the actual frame is received.

## **e1381: eSCI: LIN Wakeup flag set after aborted LIN frame transmission**

**Errata type:** Errata

**Description:** If the eSCI module is transmitting a LIN frame and the application sets and clears the LIN Finite State Machine Resync bit in the LIN Control Register 1 (eSCI\_LCR1[LRES]) to abort the transmission, the LIN Wakeup Receive Flag in the LIN Status Register may be set (LWAKE=1).

**Workaround:** If the application has triggered LIN Protocol Engine Reset via the eSCI\_LCR1[LRES], it should wait for the duration of a frame and clear the eSCI\_IFSR2[LWAKE] flag before waiting for a wakeup.

## **e1221: eSCI: LIN bit error indicated at start of transmission after LIN reset**

**Errata type:** Errata

**Description:** If the eSCI module is in LIN mode and is transmitting a LIN frame, and the application sets and subsequently clears the LIN reset bit (LRES) in the LIN Control register 1 (ESCI\_LCR1), the next LIN frame transmission might incorrectly signal the occurrence of bit errors (ESCI\_IFSR1[BERR]) and frame error (ESCI\_IFSR1[FE]), and the transmitted frame might be incorrect.

**Workaround:** There is no generic work around. The implementation of a suitable workaround is highly dependent on the application and a workaround may not be possible for all applications.

**How to Reach Us:****Home Page:**[freescale.com](http://freescale.com)**Web Support:**[freescale.com/support](http://freescale.com/support)

Information in this document is provided solely to enable system and software implementers to use Freescale products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document.

Freescale reserves the right to make changes without further notice to any products herein. Freescale makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in Freescale data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. Freescale does not convey any license under its patent rights nor the rights of others. Freescale sells products pursuant to standard terms and conditions of sale, which can be found at the following address: [freescale.com/SalesTermsandConditions](http://freescale.com/SalesTermsandConditions).

Freescale, the Freescale logo, AltiVec, C-5, CodeTest, CodeWarrior, ColdFire, ColdFire+, C-Ware, Energy Efficient Solutions logo, Kinetis, mobileGT, PowerQUICC, Processor Expert, QorIQ, Qorivva, StarCore, Symphony, and VortiQa are trademarks of Freescale Semiconductor, Inc., Reg. U.S. Pat. & Tm. Off. Airfast, BeeKit, BeeStack, CoreNet, Flexis, Layerscape, MagniV, MXC, Platform in a Package, QorIQ Qonverge, QUICC Engine, Ready Play, SafeAssure, SafeAssure logo, SMARTMOS, Tower, TurboLink, Vybrid, and Xtrinsic are trademarks of Freescale Semiconductor, Inc. All other product or service names are the property of their respective owners.

© 2013 Freescale Semiconductor, Inc.

