## **3 Volt Intel StrataFlash<sup>®</sup> Memory** 28F128J3A, 28F640J3A, 28F320J3A

**Specification Update** 

April 2002

**Notice:** The 28F128J3A, 28F640J3A, and 28F320J3A may contain design defects or errors known as errata that may cause the product to deviate from published specifications. Current characterized errata are documented in this specification update.

Information in this document is provided in connection with Intel<sup>®</sup> products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at http://www.intel.com.

#### Copyright © Intel Corporation, 2002

AlertVIEW, i960, AnyPoint, AppChoice, BoardWatch, BunnyPeople, CablePort, Celeron, Chips, Commerce Cart, CT Connect, CT Media, Dialogic, DM3, EtherExpress, ETOX, FlashFile, GatherRound, i386, i486, iCat, iCOMP, Insight960, InstantIP, Intel, Intel logo, Intel IS86, Intel/486, Intel/A90, IntelDX2, IntelDX4, IntelSX2, Intel ChatPad, Intel Create&Share, Intel Dot.Station, Intel GigaBlade, Intel Insuisness, Intel Inside, Intel Inside logo, Intel NetBurst, Intel NetBurst, Intel Net Play, Intel Play, Intel Pocket Concert, Intel Signal Structure, Intel StrataFlash, Intel TeamStation, Intel WebOutfitter, Intel Xeon, Intel XScale, Itanium, JobAnalyst, LANDesk, LanRover, MCS, MMX, MMX logo, NetPort, NetportExpress, Optimizer logo, OverDrive, Paragon, PC Dads, PC Parents, Pentium, Pentium II Xeon, Pentium III Xeon, Performance at Your Command, ProShare, RemoteExpress, Screamline, Shiva, SmartDie, Solutions960, Sound Mark, StorageExpress, The Computer Inside, The Journey Inside, This Way In, TokenExpress, Trillium, Vivonic, and VTune are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\*Other names and brands may be claimed as the property of others.

# int<sub>e</sub>l<sub>®</sub> Contents

Revision History	5
Preface	7
Summary Table of Changes	8
Identification Information	11
Errata	14
Specification Changes	19
Specification Clarifications	23
Documentation Changes	23

## **Revision History**

Date	Version	Description
07/07/99	-001	Original version
07/27/99	-002	First public release (Document includes all known errata and specification changes to date.)
10/28/99	-003	Added A-3 Stepping and Errata Added: Erratum #6, <i>Read Parameter</i> $t_{ELQX}$ Added: Erratum #7, <i>Read Parameter</i> $t_{ELAV}$ Added: Erratum #8, <i>Read Parameter</i> $t_{ELQV}$ deleted
12/09/99	-004	Specification Change: 5 Volt I/O operation removed
03/21/00	-005	Changed: Component Ordering Specifications Added: FPO Mark Identification Added: Erratum #9, <i>Write Parameter t<sub>WHRL</sub></i> Added: Erratum #10, <i>Erase Suspend Latency t<sub>WHRH</sub></i> Added: Erratum #11, <i>Erase Suspend</i> Changed: Erratum #5 Operating Temperature Range Added: Specification Change #6, <i>Operating Temperature Range</i> Added: Specification Change #7, <i>I<sub>CCR</sub></i> Added: Specification Change #8, <i>Program and Erase Time</i> with changes to Write Buffer, Block Program, Byte Program and Max Erase Time specifications Added: Specification Change #9, <i>Block Lock-Bit and Clear Times</i> with changes to the Clear Lock-Bit and Set Lock-Bit specifications Added: Specification Clarification #1, <i>Set Read Configuration Command</i>
04/17/00	-006	Split Erratum #11 into two Errata Added: Erratum #12, <i>Erase Suspend 2</i> Updated Errata tables to reflect correct Errata conditions based on FPO mark Updated Component Ordering Specifications
07/17/00	-007	Changed: Component Ordering Specifications Added: Erratum #13, <i>Program Suspend Latency t<sub>WHRH1</sub></i> Corrected Specification Change #2, typical erase time should be 1.0 sec Corrected Specification Change #8, max program time value should be 2.4 sec, typical erase time should be 1.0 sec.
10/15/00	-008	Changed: Separated Errata table 28F640J3A/28F320J3A into two tables– 28F640J3A and 28F320J3A Added: Erratum #14, <i>Erase Suspend to Program</i> Added: Erratum #15, <i>Program Suspend</i> Added: Erratum #16, <i>110ns Read Speed</i>
11/06/00	-009	Added: Erratum #17, <i>Standby Current (I<sub>CCS</sub>)</i> Minor text edits for clarification of Errata Nos. 14, 15, 16, 17
12/04/00	-010	Added component ordering information for the 32M errata #16 and #17
2/12/01	-011	Updated Errata #9, #13 and #16 status from Fix to NoFix Updated Errata #14, #15 and #17 status from Fix to Fixed Added Specification Changes #10, #11 and #12 Added B0 stepping to 128M errata table; added B0 stepping to 32M errata table Minor text edits for clarification of Errata #6

T

## int<sub>el</sub>.

Date	Version	Description
07/25/01	-012	Updated Errata #5 status from Eval to Fixed Added latest S-Spec information Added Specification Changes #13 – #17 Added Documentation Changes #1 and #2
10/29/01	-013	Added Specification Changes #18 and #19
04/16/02	-014	Added Specification Change #20 and updated Ordering and Errata information

# int<sub>ط</sub> *Preface*

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This document is a compilation of device and documentation errata and specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

## Affected Documents/Related Documents

Title	Order
3 Volt Intel StrataFlash <sup>®</sup> Memory; 28F128J3A, 28F640J3A, 28F320J3A (x8/x16) datasheet	290667-011

## **Nomenclature**

Errata are design defects or errors. These may cause the 3 Volt Intel® StrataFlash<sup>™</sup> Memory's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.



## **Summary Table of Changes**

The following table indicates the errata, specification changes, specification clarifications, or documentation changes which apply to the 3 Volt Intel StrataFlash memory components. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

## **Codes Used in Summary Table**

## Stepping

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark)	
or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

## Page

ment.
l

## **Status**

Doc:	Document change or update will be implemented.
Fix:	This erratum is intended to be fixed in a future step of the component.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Eval:	Plans to fix this erratum are under evaluation.

## Row

Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.

## Errata

	28F128J3A (128Mbit)											
	Number	Stepping				FPO Mark (9th digit)			Page	Status	Errata	
I -		<b>A</b> 1	A2	A3	<b>B</b> 0	Α	В	С	D			
	1	Х	Х							14	Fixed	Programming Time Parameters
	2	Х	Х							14	Fixed	Block Erase Time
	3	х								14	Fixed	Electrostatic Discharge Protection
1	4	Х	Х	х	Х	Х	х	х	Х	15	NoFix	5-Volt I/O Operation
1	5		Х			Х	Х			15	Fixed	Operating Temperature Range
	6	Х	Х							15	Fixed	Read Parameter t <sub>ELQX</sub>
	7	Х	Х							15	Fixed	Read Parameter t <sub>ELAV</sub>
	8	Х	Х							15	Fixed	Read Parameter t <sub>ELQV</sub> Deleted
1	9	Х	Х	Х	Х	Х	Х	Х	Х	16	NoFix	Write Parameter t <sub>WHRL</sub>
	10	Х	Х	Х		Х				16	Fixed	Erase Suspend Latency t <sub>WHRH</sub>
	11	Х	Х	Х		Х				17	Fixed	Erase Suspend Command
	12	Х	Х	Х						17	Fixed	Erase Suspend Command 2
I	13	х	х	х	х	х	х	х	х	17	NoFix	Program Suspend Latency t <sub>WHRH1</sub>
	14	Х	Х	Х		Х	Х			17	Fixed	Erase Suspend to Program

28F640J3A (64Mbit)								
Number	Step	pings	FPO (9th	Mark digit)	Page	Status	Errata	
	<b>A</b> 0	A1	В	С				
9	Х	Х	Х	Х	16	NoFix	Write Parameter t <sub>WHRL</sub>	
10	Х				16	Fixed	Erase Suspend Latency t <sub>WHRH</sub>	
11	Х				17	Fixed	Erase Suspend	
13	Х	Х	Х	Х	17	NoFix	Program Suspend Latency t <sub>WHRH1</sub>	
15	Х				18	Fixed	Program Suspend	

28F128J3A,	28F640J3A,	28F320J3A	Specification	Update
				•

	28F320J3A (32Mbit)							
Number	Steppings			Page	Status	Erroto		
Number	<b>A</b> 0	<b>B0</b>		– raye	Status	Eridid		
9	Х	Х		16	NoFix	Write Parameter t <sub>WHRL</sub>		
10	Х			16	Fixed	Erase Suspend Latency t <sub>WHRH</sub>		
11	Х			17	Fixed	Erase Suspend		
13	Х	Х		17	NoFix	Program Suspend Latency t <sub>WHRH1</sub>		
16	Х	Х		18	NoFix	110ns Read Speed		
17	Х			18	Fixed	Standby Current (I <sub>CCS</sub> )		

## **Specification Changes**

Number	Page	Specification Changes
1	19	Read Parameters for the 28F320J3A Have Been Changed to 100 ns
2	19	Block Erase Time Increased
3	19	Block Lock and Unlock Latencies Have Been Increased
4	19	Maximum Standby Current (I <sub>CCS</sub> Max) Increased to 120 $\mu$ A
5	20	5 Volt I/O Operation Removed
6	20	Operating Temperature Range
7	20	I <sub>CCR</sub>
8	20	Program and Erase Time
9	21	Block Lock-Bit Set and Clear Times
10	21	Write Parameter t <sub>WHRL</sub> increased to 500ns
11	21	Program Suspend Latency t <sub>WHRH1</sub> increased to 75µs
12	21	Read speed access increased to 110ns for 28F320J3
13	21	Operating Temperature Range
14	21	Read Parameter t <sub>EHQZ</sub> reduced to 35 ns
15	21	Write Parameter t <sub>WHEH</sub> reduced to 0 ns
16	22	Lock-Bit and Suspend Latency parameter adjustments for -40°C added
17	22	Lockout Voltage increased to 2.2 V
18	22	Read Parameter t <sub>APA</sub> reduced to 25 ns for 2.7 V - 3.6 V range
19	22	Read Parameter t <sub>GLQV</sub> reduced to 25 ns for 2.7 V - 3.6 V range
20	22	Clear Block Lock-Bits Time parameter adjustment for -40°C added

## **Specification Clarifications**

Number	Page	Specification Clarifications
1	23	Set Read Configuration Command

T

L

T

T

T

## **Documentation Changes**

Number	Page	Document Revision	Documentation Changes
1	23	-012	Error in Section 6.6, Note #4
2	23	-012	Error in Section 6.4, Note #4

## **Identification Information**

## **Component Ordering Specifications**

128-Mb A-1 Stepping	g: Errata #1	–5; Specification Change #4			
E28F128J3A-150	F128J3A-150     N/A       N/A     N/A				
128-Mb A-2 Stepping: Errata #1, 2, 4–7; Specification Change #4					
E28E128 13A-150	Q588	2-piece tape/tube			
2201 120034-130	Q589	100-piece tape and reel			
RC28E128.I3A-150	Q594	2-piece tape/tube			
	Q595	100-piece tape and reel			
128-Mb A-3 Stepping: Errata #4, 9–12; Specification Change #2–9					
	B93	2-piece tape/tube			
E28F128J3A-150	SL3ZK	72-piece tray			
	SL3ZL	96-piece tape/tube			
RC28F128J3A-150	SB93	2-piece tape/tube			
	Q679	100-piece tape and reel			
128-Mb A-3 Stepping	g: Errata #4	, 9 10,11; Specification Change #2–9			
E28F128J3A-150	SB48	Tape/tube, ninth letter in FPO mark will have "A"			
RC28F128J3A-150	0010	Tray, ninth letter in FPO mark will have "A"			
128-Mb A-3 Stepping	g: Errata # 9	); Specification Change #2–9			
E28F128J3A-150	SB48	Tape/tube, ninth letter in FPO mark will have "B"			
RC28F128J3A-150	0010	Tray, ninth letter in FPO mark will have "B"			
128-Mb A-3 Stepping	g: Errata #9	,13; Specification Change #2-11, 17			
	SL56C	2-pc tube			
E28F128J3A-150	833865	96-pc tray			
	SL56D	1600-pc tape & reel			
	SL56C	2-pc tube			
RC28F128J3A-150	SL56J	144-pc tray			
RC28F128J3A-150 128-Mb A-3 Steppi E28F128J3A-150 RC28F128J3A-150 128-Mb A-3 Steppi E28F128J3A-150 RC28F128J3A-150 RC28F128J3A-150 RC28F128J3A-150 I28-Mb A-3 Steppi E28F128J3A-150 RC28F128J3A-150 RC28F128J3A-150	SL56D	2000-pc tape & reel			



T

128-Mb B-0 Stepping	g: Errata #9	,13; Specification Change #2-5, 7-11, 13-20 *MOST RECENT*
	SL56L	2-pc tube
E28F128J3A-150	SL56K	96-pc tray
	SL56D	1600-pc tape & reel
	SL56L	2-pc tube
RC28F128J3A-150	SL56K	144-pc tray
	SL56M	2000-pc tape & reel
64-Mb A-0 Stepping	: Errata #9–	11; Specification Change #1–9
E28E640 13A-120	Q684	2-piece tape/tube
L201 04033A-120	Q685	100-piece tape/reel
RC28E640 13A-120	Q686	2-piece tape/tube
10201 040034-120	Q687	100-piece tape/reel

64-Mb A-0 Stepping	i4-Mb A-0 Stepping: Errata #5, #9–11; Specification Change #1–9				
	Default	96 tray			
E28F640J3A-120	SB48	1600-piece tape/reel			
	SB93	2-piece tube			
64-Mb A-0 Stepping	: Errata #5,	#9; Specification Change #1–9			
	Default	144 tray			
RC28F640J3A-120	SB48	2000-piece tape/reel			
	SB93	2 piece tube			
64-Mb A-1 Stepping: Errata #9, #13; Specification Change #2-5, 7–11, 13-20 *MOST RECENT*					
E28F640J3A-120	SL5AR	2-pc tube			
	SL5AQ	96-pc tray			
	SL5AS	1600-pc tape & reel			
	SL5AR	2-pc tube			
RC28F640J3A-120	SL5AQ	144-pc tray			
	SL5AS	2000-pc tape & reel			
32-Mb A-0 Stepping	: Errata #16	, #17; Specification Change #1–9			
	Default	96 piece tray			
E28F320J3A-110	SB10	1600 piece tape/reel			
	Q-A03	2 piece tube			
32-Mb B-0 Stepping	: Errata #9,	#13, #16; Specification Change #2-5, 7-20 *MOST RECENT*			
	SB93	2-pc tube			
E28F320J3A-110	834996	96-pc tray			
	SB48	1600-pc tape & reel			
	SB93	2-pc tube			
RC28F320J3A-110	834965	144-pc tray			
	SB48	2000-pc tape & reel			

### NOTES:

Q-spec order numbers correspond to sample units.
 S-spec order numbers correspond to production (qualified) units.

## Errata

## 1. Programming Time Parameters

Problem:

The table below summarizes the programming time parameters.

## Block Erase, Program, and Lock-Bit Configuration Performance<sup>(1,2,3)</sup>

#	Sym	Parameter	Notes	Тур	Max	Unit
W16		Write Buffer Byte Program Time (Time to Program 32 bytes/16 words)	4,5,6,7	384	TBD	μs
W16	t <sub>WHQV3</sub>	Byte Program Time (Using Word/Byte Program Command)	4	360	TBD	μs
	t <sub>EHQV3</sub>	Block Program Time (Using Write to Buffer Command)	4	1.6	TBD	sec

#### NOTES:

- Typical values measured at T<sub>A</sub> = +25 °C and nominal voltages. Assumes corresponding lock-bits are not set. Subject to change based on device characterization.
- 2. These performance numbers are valid for all speed versions.
- 3. Sampled but not 100% tested.
- 4. Excludes system-level overhead.
- 5. These values are valid when the buffer is full, and the start address is aligned on a 32-byte boundary.
- 6. Effective per-byte program time ( $t_{WHQV1}$ ,  $t_{EHQV1}$ ) is 6.8 µs/byte (typical)
- 7. Effective per-word program time ( $t_{WHQV2}$ ,  $t_{EHQV2}$ ) is 13.6 µs/word (typical)
- 8. Max values are measured at worst case temperature and  $V_{CC}$  corner after 100k cycles
- Implication: Both methods to program the flash memory are affected by this erratum: using the 32-byte write buffer and using the single byte/word program command.
- Workaround: No workaround(s) has been identified for this erratum.
- Status: This is intended to be fixed in future steppings. Refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s). This is fixed on A3 and above steppings.

### 2. Block Erase Time

- Problem: The typical time required to erase one 128-Kbyte block is 2.0 sec and the maximum time is 25 sec.
- Implication: System designers should be aware of this specification as it could impact system operation or performance.
- Workaround: No workaround(s) has been identified for this erratum.
- Status: This is intended to be fixed in future steppings. Refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s). This is fixed on A3 and above steppings.

### 3. Electrostatic Discharge Protection

Problem: Input and I/O pins fail Intel's internal electrostatic discharge (ESD) specification.

- Implication: Customers may experience leakage currents on input and I/O pins greater than 1 µA. Parts that have failed Intel's ESD testing exhibited leakage currents greater than 1 µA.
- Workaround: Customers should not perform ESD testing on these components. The parts do not require any special handling and may be used in a normal system. However, specific ESD testing on the component should not be performed until a future stepping of the device that corrects this erratum.

Status:	This erratum is fixed. Refer to the <i>Summary Tables of Changes</i> to determine affected product(s) and stepping(s). This is fixed on A2 and above steppings.
4.	5-Volt I/O Operation
Problem:	The 5-Volt I/O feature of this flash memory is not supported.
Implication:	The flash memory does not support 5 V levels on its outputs or its inputs. This includes address, data, and control pins.
Workaround:	Provide a 3 V interface to the flash memory I/O pins of capable systems.
Status:	This will not be fixed in future steppings. Refer to the <i>Summary Tables of Changes</i> to determine affected product(s) and stepping(s).
5.	Operating Temperature Range
Problem:	The operating temperature range for this device is 0 $^\circ C$ to +70 $^\circ C.$ with a –20 $^\circ C$ read only operation.
Implication:	Customers that use this part in applications that require full device operation below 0 $^{\circ}$ C should be aware of this erratum. Full operation of the device below 0 $^{\circ}$ C is not guaranteed and should not be attempted. The device will read down to -20 $^{\circ}$ C.
Workaround:	No workaround(s) has been identified for this erratum.
Status:	This erratum is valid for 128M A-0, A1, and A-2 steppings and was fixed in subsequent steppings. Refer to the <i>Summary Tables of Changes</i> to determine affected product(s) and stepping(s).
6.	Read Parameter t <sub>ELQX</sub>
Problem:	Devices need the parameter $t_{ELQX}$ =150 ns minimum. CE low to output in low Z ( $t_{ELQX}$ ) is designated as R6 in Figure 1, in this Specification Update revision.
Implication:	Higher volume prototype testing could experience read failures if this erratum is ignored.
Workaround:	Use devices for initial lower volume prototype development.
Status:	This is intended to be fixed in future steppings. Refer to the <i>Summary Tables of Changes</i> to determine affected product(s) and stepping(s). This is fixed on A3 and above steppings.
7.	Read Parameter t <sub>ELAV</sub>
Problem:	Devices need the parameter $t_{ELAV} = 500$ ns maximum. Chip Enable to Address Valid ( $t_{ELAV}$ ) is designated as R3 in Figure 1, in this Specification Update revision.
Implication:	Higher volume prototype testing could experience read failures if this erratum is ignored.
Workaround:	Use devices for initial lower volume prototype development.
Status:	This is intended to be fixed in future steppings. Refer to the <i>Summary Tables of Changes</i> to determine affected product(s) and stepping(s). This is fixed on A3 and above steppings.
8.	Read Parameter t <sub>ELQV</sub> Deleted
Problem:	The parameter t <sub>ELQV</sub> has been deleted.
Implication:	Higher volume prototype testing could experience read failures if this erratum is ignored.
Workaround:	Use devices for initial lower volume prototype development.
Status:	This is intended to be fixed in future steppings. Refer to the <i>Summary Tables of Changes</i> to determine affected product(s) and stepping(s). This is fixed on A3 and above steppings.



### Figure 1. AC Waveform for Standard Word/Byte Read Operations

NOTE: CE<sub>X</sub> low is defined as the first edge of CE<sub>0</sub>, CE<sub>1</sub>, or CE<sub>2</sub> that enables the device. CE<sub>X</sub> high is defined at the first edge of CE<sub>0</sub>, CE<sub>1</sub>, or CE<sub>2</sub> that disables the device (see Table 2, *Chip Enable Truth Table*). When reading the flash array, a faster t<sub>GLQV</sub> (R16) applies. Non-array reads refer to status register reads, query reads, or device identifier reads.

## 9. Write Parameter t<sub>WHRL</sub>

Problem: The parameter t<sub>WHRL</sub> has been extended to 500 ns.

- Implication: Customer may not see the device ready when using the STS pin.
- Workaround: Customer should allow a minimum of 500 ns before polling the STS pin after WE# goes high when erasing or programming the device.
- Status: This will not be fixed in future steppings. Refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s).

## 10. Erase Suspend Latency t<sub>WHRH</sub>

Problem: The parameter  $t_{WHRH}$  has been extended to 120 µs.

- Implication: Customer may not be able to read the device after a Erase suspend for up to 120 µs.
- Workaround: There is no known work around for this issue.

Status: This is intended to be fixed in future steppings. Refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s). This is fixed on material that has a "B" in the ninth character in the FPO number.

## 11. Erase Suspend Command

- Problem: Device may not complete an erase function if an Erase Suspend Resume command sequence is given to the device.
- Implication: Customers may see the suspended block partially programmed when the erase has completed. If the device locks up, the customer may not be able to perform another erase until RP# is toggled to GND.
- Workaround: The customer should verify that the erase has completed by executing a read on the array. If the device did not complete the erase, the customer should re-issue the Erase command to finish the erase function.
- Status: This is intended to be fixed in a future product release. Refer to *Identification Information* for affected product ordering information. Also refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s). This is fixed on material that has a "B" in the 9th character in the FPO number.

### 12. Erase Suspend Command 2

Problem: Device may lock up during an Erase Suspend command.

- Implication: If the device locks up, the customer may not be able to execute another erase until RP# is toggled to GND.
- Workaround: The customer should verify that the erase has completed by executing a read on the array. If the device did not complete the erase, the customer should re-issue the Erase command to finish the erase function. If the device locks up, the customer should toggle RP# to GND to recover.
- Status: This is intended to be fixed in a future product release. Refer to *Identification Information* for affected product ordering information. Also, refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s). This is fixed on material that has a "B" in the ninth character in the FPO number.

## 13. Program Suspend Latency t<sub>WHRH1</sub>

Problem: The parameter  $t_{WHRH1}$  has been extended to 75  $\mu$ s.

Implication: Customer may not be able to read the device after a Program suspend for up to 75 µs.

- Workaround: There is no known workaround for this issue.
- Status: This will not be fixed in future steppings. Refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s).

## 14. Erase Suspend To Program

- Problem: When an erase suspend operation is initiated on block X, where X = 0 to 63, the user will not be able to program any data in block X + 64.
- Implication: Customers performing an erase suspend to program operation should be aware that the program portion of this operation will not occur and that it will set status register bit-4 (SR.4 = 1).
- Workaround: There is no known work around for this issue.
- Status: This is intended to be fixed in a future product release. Refer to *Identification Information* for affected product ordering information. Also, refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s).

Errata



## 15. **Program Suspend**

- When a Write to Buffer program operation is suspended, the device can inadvertently
  reset the data in the write buffer.
- Implication: Customers performing a program suspend on a Write to Buffer command should be aware that the data in the write buffer may get reset to FFFFh. Therefore, when the program suspend is resumed, the expected data may not exist in the write buffer. Resulting in incorrect data being programmed to the array.

Workaround: There is no known work around for this issue.

Status: This is intended to be fixed in a future product release. Refer to *Identification Information* for affected product ordering information. Also, refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s).

### 16. 110ns Read Speed

Problem:Device is unable to support read accesses at 100ns.Implication:Customers should be aware that the device read access is 110ns.Workaround:There is no known work around for this issue.Status:This will not be fixed in future steppings. Refer to the Summary Tables of Changes to determine affected product(s) and stepping(s).

## 17. Standby Current (I<sub>CCS</sub>)

Problem: Maximum RMS standby current is 170uA.

- Implication: Due to the additional maximum current, customers using this device in a battery operated system should be aware of this erratum because the expected battery life may need re-evaluated.
- Workaround: There is no known work around for this issue.
- Status: This is intended to be fixed in a future product release. Refer to *Identification Information* for affected product ordering information. Also, refer to the *Summary Tables of Changes* to determine affected product(s) and stepping(s).

## Intel

## Specification Changes

#### 1. Read Parameters for the 28F320J3A Have Been Changed to 100 ns

Issue:

Several read parameters for the 28F320J3A have been changed from 90 ns to 100 ns.

The 28F320J3A read parameters t<sub>AVAV</sub> (R1), t<sub>AVOV</sub> (R2), for 3 V I/O operation have been changed from 90 ns to 100 ns. Customers who designed systems around the 90 ns parameters should be aware of these changes.

#### 2. **Block Erase Time Increased**

```
Issue:
```

The block erase time was changed. Typical block erase time is 1.0 sec, and the maximum is 5 sec. Customers should be aware that this is an increase from the 0.7 typical block erase time.

#### 3. Block Lock and Unlock Latencies Have Been Increased

Issue:

### The table below summarizes the block lock-bit parameters that have been increased.

## Block Erase, Program, and Lock-Bit Configuration Performance<sup>(1,2,3)</sup>

#	Sym	Parameter	Notes	Тур	Max	Unit
W16	t <sub>WHQV5</sub> t <sub>EHQV5</sub>	Set Lock-Bit Time	4	64	75	μs
W16	t <sub>WHQV6</sub> t <sub>EHQV6</sub>	Clear Block Lock-Bits Time	4	0.5	0.70	sec

NOTES:

1. Typical values measured at T<sub>A</sub> = +25 °C and nominal voltages. Assumes corresponding lock-bits are not set. Subject to change based on device characterization.

- 2. These performance numbers are valid for all speed versions.
- 3. Sampled but not 100% tested.
- 4. Excludes system-level overhead.
- 5. These values are valid when the buffer is full, and the start address is aligned on a 32-byte boundary.
- 6. Effective per-byte program time ( $t_{WHQV1}$ ,  $t_{EHQV1}$ ) is 6.8 µs/byte (typical).
- 7. Effective per-word program time ( $t_{WHQV2}$ ,  $t_{EHQV2}$ ) is 13.6 µs/word (typical). 8. Max values are measured at worst case temperature and V<sub>CC</sub> corner after 100k cycles.

The time required to set a block lock-bit (i.e., lock a block) and the time required to clear a block lock-bit (i.e., unlock a block) have been increased. System designers should be aware of these changes if these specification increases affect system operation or performance.

#### 4. Maximum Standby Current (I<sub>CCS</sub> Max) Increased to 120 µA

Issue:

The maximum standby current for this device is  $120 \,\mu$ A.

Customers should be aware when designing their systems based on the maximum current ratings for this device. This parameter would typically affect power consumption. By definition, the maximum standby current is the highest amount of current drawn by this device, when deselected, under the most extreme/worst conditions.



### 5. 5 Volt I/O Operation Removed

Issue: 5 Volt I/O operation is removed from all steppings.

Device damage may be experienced if this change is ignored.

## 6. Operating Temperature Range

Issue: Operating Temperature range is being changed to -25 °C to +85 °C.

## 7. I<sub>CCR</sub>

Issue: The table below summarizes the I<sub>CCR</sub> parameters that have been changed.

Symbol	Parameter	Notes	Тур	Max	Unit	Test Conditions
1	V <sub>CC</sub> Page Mode Read	134	15	20	mA	CMOS Inputs, $V_{CC} = V_{CC}$ Max, $V_{CCQ} = V_{CCQ}$ Max using standard 4 word page mode reads. Device is enabled (see Table 2 in the datasheet) f = 5 MHz, $I_{OUT} = 0$ mA
ICCR	Current	1,3,4	24	29	mA	CMOS Inputs, $V_{CC} = V_{CC}$ Max, $V_{CCQ} = V_{CCQ}$ Max using standard 4 word page mode reads. Device is enabled ((see Table 2 in the datasheet)) f = 33 MHz, $I_{OUT} = 0$ mA
I <sub>CCR</sub>	V <sub>CC</sub> Byte Mode Read Current	1,3,4	40	50	mA	CMOS Inputs, $V_{CC} = V_{CC}$ Max, $V_{CCQ} = V_{CCQ}$ Max using standard word/byte single reads Device is enabled ((see Table 2 in the datasheet)) f = 5 MHz, $I_{OUT} = 0$ mA

## 8. **Program and Erase Time**

Issue:

The table below summarizes the Program and Erase parameters that have been changed.

## Block Erase, Program, and Lock-Bit Configuration Performance<sup>(1,2,3)</sup>

#	Sym	Parameter	Notes	Тур	Max	Unit
W16		Write Buffer Byte Program Time (Time to Program 32 bytes/16 words)	4,5,6,7	218	654	μs
W16	t <sub>WHQV3</sub> t <sub>EHQV3</sub>	Byte Program Time (Using Word/Byte Program Command)	4	210	630	μs
		Block Program Time (Using Write to Buffer Command)	4	0.8	2.4	sec
W16	t <sub>WHQV4</sub> t <sub>EHQV4</sub>	Block Erase Time	4	1.0	5.0	sec

#### NOTES:

- 1. Typical values measured at  $T_A$  = +25 °C and nominal voltages. Assumes corresponding lock-bits are not set. Subject to change based on device characterization.
- 2. These performance numbers are valid for all speed versions.
- 3. Sampled but not 100% tested.
- 4. Excludes system-level overhead.
- 5. These values are valid when the buffer is full, and the start address is aligned on a 32-byte boundary.
- 6. Effective per-byte program time ( $t_{WHQV1}$ ,  $t_{EHQV1}$ ) is 6.8 µs/byte (typical).
- 7. Effective per-word program time (t<sub>WHQV2</sub>, t<sub>EHQV2</sub>) is 13.6 µs/word (typical).
- 8. Max values are measured at worst case temperature and  $V_{CC}$  corner after 100k cycles.

## Block Lock-Bit Set and Clear Times

Problem:

9.

### The table below summarizes the block lock-bit parameters that have been changed.

## Block Erase, Program, and Lock-Bit Configuration Performance<sup>(1,2,3)</sup>

#	Sym	Parameter	Notes	Тур	Max	Unit
W16	t <sub>WHQV5</sub> t <sub>EHQV5</sub>	Set Lock-Bit Time	4	64	75	μs
W16	t <sub>WHQV6</sub> t <sub>EHQV6</sub>	Clear Block Lock-Bits Time	4	0.5	0.70	sec

#### NOTES:

- 1. Typical values measured at  $T_A = +25$  °C and nominal voltages. Assumes corresponding lock-bits are not set. Subject to change based on device characterization.
- 2. These performance numbers are valid for all speed versions.
- 3. Sampled but not 100% tested.
- 4. Excludes system-level overhead.
- 5. These values are valid when the buffer is full, and the start address is aligned on a 32-byte boundary.
- 6. Effective per-byte program time ( $t_{WHQV1}$ ,  $t_{EHQV1}$ ) is 6.8 µs/byte (typical)
- 7. Effective per-word program time ( $t_{WHQV2}$ ,  $t_{EHQV2}$ ) is 13.6 µs/word (typical)
- 8. Max values are measured at worst case temperature and  $V_{CC}$  corner after 100k cycles

The time required to set a block lock bit (i.e., lock a block) and the time required to clear a block lock-bit (i.e., unlock a block) have been increased. System designers should be aware of these changes if these specification increases affect system operation or performance.

The maximum t<sub>WHRH1</sub> (W16) time has increased from 30µs to 75µs. Customers using the program

### 10. Write parameter t<sub>WHRL</sub> increased to 500ns

Problem: The maximum t<sub>WHRL</sub> (W13) time has increased from 90ns to 500ns. Customers using the STS pin should be aware of this change.

## 11. Program suspend latency t<sub>WHRH1</sub> increased to 75us

Problem:

## suspend feature should be aware of this change.

## 12. Read speed access increased to 110ns for 28F320J3

Problem: The 28F320J3 read parameters t<sub>AVAV</sub> (R1), t<sub>AVQV</sub> (R2), and t<sub>ELQV</sub> (R3) have been increased from 100 ns to 110 ns. Customers who designed systems around the 100 ns parameters should be aware of these changes.

### **13. Operating Temperature Range**

Issue: Operating Temperature range is being changed to -40 °C to 85 °C.

### 14. Read parameter t<sub>EHQZ</sub> reduced to 35 ns

Issue: Parameter  $t_{EHQZ}$  (R8) has been reduced from 55 ns(max) to 35 ns(max). Customers may now take advantage of this reduced timing.

### 15. Write parameter t<sub>WHEH</sub> reduced to 0 ns

Issue: Parameter t<sub>WHEH</sub> (W6) has been reduced from 10 ns(min) to 0 ns(min). Customers may now take advantage of this reduced timing.



#### 16. Lock-Bit and Suspend Latency parameter adjustments for –40°C added

Issue:

The table below summarizes the Lock-Bit and Suspend Latency parameters that have been changed.

## Block Erase, Program, and Lock-Bit Configuration Performance<sup>(1,2,3)</sup>

#	Sym	Parameter	Notes	Тур	Max	Unit
W16	t <sub>WHQV5</sub> t <sub>EHQV5</sub>	Set Lock-Bit Time	4,9	64	75/85	μs
W16	t <sub>WHRH1</sub> t <sub>EHRH1</sub>	Program Suspend Latency Time to Read	9		75/90	μs
W16	t <sub>WHRH</sub> t <sub>EHRH</sub>	Erase Suspend Latency Time to Read	9		35/40	μs

#### NOTES:

- 1. Typical values measured at T<sub>A</sub> = +25 °C and nominal voltages. Assumes corresponding lock-bits are not set. Subject to change based on device characterization.
- 2. These performance numbers are valid for all speed versions.
- 3. Sampled but not 100% tested.
- 4. Excludes system-level overhead.
- 5. These values are valid when the buffer is full, and the start address is aligned on a 32-byte boundary.
- 6. Effective per-byte program time ( $t_{WHQV1}$ ,  $t_{EHQV1}$ ) is 6.8 µs/byte (typical).
- Effective per-word program time (t<sub>WHQV2</sub>, t<sub>EHQV2</sub>) is 13.6 μs/word (typical). 8. Max values are measured at worst case temperature and V<sub>CC</sub> corner after 100k cycles (except as noted).

Parameter t<sub>APA</sub> (R15) has been reduced from 30 ns(max) to 25 ns(max) on the 2.7 V - 3.6 V range.

Previously, 25 ns was only granted on the 3.0 V - 3.6 V range. Customers may now take advantage

9. Max values are expressed at -25 °C/-40 °C.

#### 17. Lockout Voltage increased to 2.2 V

 $V_{\mbox{PENLK}}$  and  $V_{\mbox{LKO}}$  are being changed from 2.0 V to 2.2 V. Customers who use voltages in this Issue: range should be aware of these changes.

#### 18. Read parameter t<sub>APA</sub> reduced to 25 ns

of this reduced timing.

Issue:

#### 19. Write parameter t<sub>GLQV</sub> reduced to 25 ns

Parameter t<sub>GLOV</sub> (R16) has been reduced from 30 ns(max) to 25 ns(max) on the 2.7 V - 3.6 V Issue: range. Previously, 25 ns was only granted on the 3.0 V - 3.6 V range. Customers may now take advantage of this reduced timing.

#### 20. Clear Block Lock-Bits Time parameter adjustment for –40°C added

Issue:

The table below summarizes the Clear Block Lock-bits parameter that has been changed.

#	Sym	Parameter	Notes	Тур	Max	Unit
W16	t <sub>WHQV6</sub> t <sub>EHQV6</sub>	Clear Block Lock-Bits Time	4,10	0.5	0.70/ 1.4	sec

#### Notes:

4. Excludes system-level overhead.

10. Max values are expressed at 25 °C/-40 °C.

## **Specification Clarifications**

## 1. Set Read Configuration Command

Status:

Changed Section 4.11, *Set Read Configuration Command*, and Section 4.11.1, *Read Configuration*, as follows:

4.11: This command is not supported on this product. This device defaults to the asynchronous page mode. If this command is given to the device, it will not affect the operation of the device.

4.11.1: The device supports both asynchronous page mode and standard word/byte reads. No configuration is required.

Status register, and identifier support standard word/byte single read operations.

## **Documentation Changes**

## 1. Error in Section 6.6, Note #4

Issue:

Note #4 in Section 6.6 was changed as follows:

#### OLD:

4. Write pulse width (t<sub>WP</sub>) is defined from CE<sub>X</sub> or WE# going low (whichever goes low first) to CE<sub>X</sub> or WE# going high (whichever goes high first). Hence, t<sub>WP</sub> = t<sub>WLWH</sub> = t<sub>ELEH</sub> = t<sub>WLEH</sub> = t<sub>ELWH</sub>. If CEx is driven low 10 ns before WE# going low, WE# pulse width requirement decreases to t<sub>WP</sub> - 10 ns.

#### NEW:

4. Write pulse width (t<sub>WP</sub>) is defined from CE<sub>X</sub> or WE# going low (whichever goes low last) to CE<sub>X</sub> or WE# going high (whichever goes high first). Hence, t<sub>WP</sub> = t<sub>WLWH</sub> = t<sub>ELEH</sub> = t<sub>WLEH</sub> = t<sub>ELWH</sub>

### 2. Error in Section 6.4, Note #4

Issue:

Note #4 in Section 6.4 was obsoleted by Specification Change #6 and #13 (Operating Temperature Range). It was deleted and the remaining notes were re-numbered.