
# **Multi-channel Controller** Series PSE200



#### Option

bly optional parts are required, order with the part numbers listed below

when only optional parts are required, order with the part humbers listed beio			
Description	Part no.	Note	
Panel mount adapter	ZS-26-B	Waterproof seal, screws included	
Front protective cover	ZS-26-01		
Front protective cover + Panel mount adapter	ZS-26-C	Waterproof seal, screws included	
	ZS-26-D	$\Box$ 48 conversion adapter	
□48 conversion adapter This adapter is used to mount Series PSE200 on the panel fitting of Series PS100.	Order papel p	nount adapter separately.	
	· ·	,	
Connector	ZS-26-6	E (4 pcs. per set)	

**SMC** 

# Multi-channel Controller Series PSE200

#### Specifications

	Model	PS	E200	PSE	201		
Output specification		NPN open collector PNP open collector			n collector		
Power supply voltage		12 to 24 VDC ±10%, Ripple (p-p) 10% or less (With power supply polarity protection)					
Current consumption		55 mA or less (Current consumption for sensor is not included.)					
Power supply vo	oltage for sensor		[Power supply	voltage] –1.5 V			
Power supply cu	urrent for sensor Note 1)	40 mA maximum (100	mA maximum for the tota	power supply current whe	n 4 sensors are input.)		
Sensor input			1 to 5 VDC (Input impedance: Approx. 800 kΩ)				
	No. of inputs		4 in	puts		<b>ZSE</b> □	
	Input protection		With excess voltage p	rotection (Up to 26.4 V)		ISE□	
I bastansa'a	Hysteresis mode		Var	iable		PSE	
Hysteresis	Window comparator mode		3-digit fixed			IUL	
	No. of outputs		5 outputs (CH1: 2 outp	uts, CH2 to 4: 1 output)		<sup>z</sup> SE3	
	Maximum load current		80	mA			
Switch output	Maximum load voltage		30 VDC (	With NPN)		PS	
	Residual voltage		1 V or less (With loa	ad current of 80 mA)		10	
	Output protection		With short cir	cuit protection			
Response time			5 ms	or less			
	Anti-chattering function	With anti-cha	• •	e time selection: 20 ms, 16	0 ms, 640 ms	ZSP	
Repeatability				S. or less			
Setting/Display	accuracy	±0.5% F.S. ±1 digit or less (at ambient temperature of 25° ±3°C)				ISA2	
Display		For measured value display: 4-digit, 7-segment indicator, Display color: Yellow For channel display: 1-digit, 7-segment indicator, Display color: Red					
Indication light		Red (Lights up when output is ON.)					
Auto shift input		Non-voltage input (Reed or Solid state), Input 10 ms or more, Independently controllable auto shift function ON/OFF					
Auto identification	on function Note 2)	With auto identification function					
	Enclosure	Front face: IP65, Other: IP40			PF2□		
	Ambient temperature range	Operating: 0° to 50°C, Stored: -10° to 60°C (No freezing or condensation)					
Resistance	Ambient humidity range	Operating/Stored: 35 to 85% RH (No condensation)			IF□		
	Vibration resistance	10 to 500 Hz at whichever is smaller of 1.5 mm amplitude or 98 m/s <sup>2</sup> acceleration, in X, Y, Z directions for 2 hrs. each (De-energized)					
	Impact resistance	980 m/s <sup>2</sup> in X, Y, Z directions, 3 times each (De-energized)			Data		
Temperature characteristics		±0.5% F.S. or less based on 25°C					
Connection		Power supply/Output connection: 8P connector, Sensor connection: 4P connector					
Material		Enclosure: PBT; Display: Transparent nylon; Back rubber cover: CR					
Weight		Approx. 60 g (Power supply/output connecting cable not included)					
Applicable pressure sensor		PSE530 (For high pressure)	PSE531 (For vacuum)	PSE532 (For low pressure)	PSE533 (For compound pressure)		
Regulating pres	ssure range	-0.1 to 1 MPa	10 to -101 kPa	-10 to 101 kPa	-101 to 101 kPa		
	kPa		0.1	0.1	0.1		
Note 3 Set pressure resolution	MPa	0.001	—	_	—		
	te 3) kgf/cm <sup>2</sup>	0.01	0.001	0.001	0.001		
	bar	0.01	0.001	0.001	0.001		
	psi	0.1	0.01	0.01	0.02		
	mmHg	_	1	_	1		
	InHg	-	0.1	—	0.1		

Note 1) If the Vcc and 0 V side of the sensor input connector are short circuited, the inside of the controller will be damaged. Note 2) Auto identification function comes with "Series PSE53 " pressure sensor only. Other SMC series (PSE510 and PSE520) are not equipped with this function.

Note 3) For controllers with unit display switching function. (Either of SI units, [kPa] or [MPa], will be the set unit for those controllers without unit switching function.)


2 3 4

0 0

00000

#### Dimensions

#### **PSE200 & PSE201**




#### Sensor connector (4P x 4)


1

-2


-3

4






#### **Connector (Option)**




#### Power supply/Output connector (8P)



PIN no.	Terminal	
1	DC (+)	
2	DC (-)	
3	CH1_OUT1	
(4)	CH1_OUT2	
5	CH2_OUT1	
6	CH3_OUT1	
7	CH4_OUT1	
8	Auto shift input	

#### Power supply/Output connection cable (Included)





#### Dimensions

Front protective cover + Panel mount




□48 conversion adapter + Panel mount





ZSE□ ISE□
PSE
<sup>z</sup> SE3
PS
$^{\mathbf{Z}}_{\mathbf{I}}\mathbf{SE}^{1}_{2}$
ZSP
ISA2
IS□
ZSM
<b>PF2</b> □
<b>IF</b>
Data






#### Descriptions

# **4-digit display**Displays the measured pressure value, content for each setting, and error code. **Switch output display**Displays the output status of OUT1 (CH1 to CH4), OUT2 (CH1 only). Lights up when it is ON. **UP button**Use this button to change the mode or set value. **SET button**

Use this button to set the mode or set value.



#### Unit display

The selected unit lights up. Use unit labels for units other than MPa and kPa.

#### Unit labels

kgf/cm<sup>2</sup> bar PSI inHg mmHg

#### Channel display

Displays the selected channel.

#### **DOWN** button


Use this button to change the mode or set value.

#### **Error Code & Solution**


LED display	Contents	Solution		
Er l	Excess current is flowing into the switch output of OUT1.	Shut off the power supply. After eliminating the output factor that		
Excess current is cau flowing into the current		caused the excess current, turn the power supply back on.		
Er 3	Pressure is applied to a pressure sensor during the reset operation (a zero point adjustment) as follows: When compound pressure is used: $\pm 2.5\%$ F.S. or more. When pressure other than compound pressure is used: $\pm 5\%$ F.S. or more. * After displaying for 2 seconds, it will return to the measuring mode.	Bring the pressure back to atmospheri pressure and use the reset function (zero point adjustment) again.		
	Supply pressure exceeds the maximum regulating pressure.	Reduce/Increase supply pressure to		
	Supply pressure is below the minimum regulating pressure.	within the regulating pressure range.		
Er S	Internal data error.	Please contact SMC		
Er B	Internal data error.	Chuit off the neuron		
Er 7	Internal data error.	Shut off the power supply and turn it back on. Please contact SMC if it does not recover.		
Er 8	Internal data error.			

#### Internal Circuit and Connection

#### PSE200-(M)□ • NPN open collector 5 outputs + Auto shift 1 input specification




#### PSE201-(M)□ • PNP open collector 5 outputs + Auto shift 1 input specification




# Multi-channel Controller/Pressure Sensor Series PSE530/200

#### **Operation 1: Initial Setting**




#### **Operation 1: Initial Setting**

#### 4 Response time setting










CH1 setting is completed when the channel display changes from blinking to lights on. Repeat the same setting steps for CH2 to CH4.

# Multi-channel Controller/Pressure Sensor Series PSE530/200

#### **Operation 2: Pressure Setting**


#### Manual setting



To measuring mode

#### **Operation 2: Pressure Setting**

#### Auto preset



Work n

Work 2

Work n

 $ON = A - \frac{A - B}{4}$ 

 $OFF = B + \frac{A - B}{4}$ 




# Multi-channel Controller/Pressure Sensor Series PSE530/200

#### **Operation 3: Special Setting**

press SET

Proceed to the

auto shift mode





**SMC** 

SET Setting is complete.

Return to the copy mode.

#### **Operation 3: Special Setting**






#### **Function Details**

#### A Display calibration function

This function eliminates slight differences in the output values of all 4 channels and allows uniformity in the numbers displayed. Displayed values of the pressure sensors can be adjusted to within  $\pm 5\%$ .



— Displayed value at the time of shipment

Adjustable range of display calibration function

Note) When the display calibration function is used, the regulating pressure value may change  $\pm 1$  digit.

#### C Auto shift function

If there is a fluctuation in the supply pressure, erroneous operation may occur (e.g., in the case of adsorption verification, the switch does not turn ON even though the workpiece is being adsorbed, or does not turn OFF even though the workpiece is no longer being adsorbed.)

The auto shift function rectifies pressure changes to ensure proper ON/OFF switch response during such fluctuations.

#### <Principle>

At the point when the supply pressure fluctuates, the set pressure value is rectified by setting the auto shift input (external input) to Lo (no-voltage input), using the pressure measured at that point as a standard.

- This function is good only for those channels whose function selection is turned "on" during the auto shift mode setting.
- Maintain the constant pressure for 10 ms or more after a drop in the auto shift input.
- When the auto shift is input, "ooo" will be displayed for approximately 1 second, and the pressure value at that point will be saved as a rectified value "C\_5" (for CH1) or "C\_3" (for CH2 and CH3). Based on the saved rectified values, the set value "P\_1" to "P\_4" or "n\_1" to "n\_4" will likewise be rectified.
- The time from the moment the auto shift is input, to the moment the switch output actually operates is 15 ms or less.
- If the set value rectified by the auto shift input exceeds the regulating pressure range, it will be rectified once more to within the values of the regulating pressure range.
- When the auto shift function is turned "off", the shift value will be zero.
- When all of the auto shift functions are turned "off", "ooo" will not be displayed even if the auto shift input is set to Lo (no-voltage input).
- Values "C\_5" and "C\_3", rectified after the auto shift is input, will be lost once the power is turned off.
- Values "C\_5" and "C\_3", rectified after the auto shift function is used, will be reset to zero (initial value) when the power is turned back on again.

Note) Rectified values are not saved in EEPROM.

#### **D** Auto identification function

This function automatically identifies the pressure range of the pressure sensor that is connected to the multi-channel pressure sensor controller, thus eliminating the need of having to reset the range again after replacing the sensor. This function will be activated either when "Aon" is set in the auto identification mode or when the power is turned back on in that condition. However, this function only works in conjunction with specific pressure sensors (SMC Series PSE53□). When other pressure sensors are used, this function will not work. When using other types of pressure sensors, first set the auto identification mode to "AoF", and then proceed to setting the range. Turning the power back on while in the "Aon" setting can cause a malfunction.


#### **B** Copy function


Information that can be copied includes the following: 1 Pressure set values, 2 Range settings, 3 Display Units, 4 Output modes, 5 Response times.

- When CH1 is copied to CH2, CH3, and CH4, information of OUT1 in CH1 will be copied.
- When CH2, CH3, or CH4 is copied to CH1, information of OUT1 in CH2, CH3, or CH4 will be copied only to OUT1 in CH1.
- Note) When the copy function is used, the regulating pressure value of the copied channel may change  $\pm 1$  digit.

When auto shift is NOT used:

When the supply pressure fluctuates, a correct sensing is no longer possible.





#### E Unit display switching function

Display units can be switched with this function.

Units that can be displayed vary depending on the range of the pressure sensors connected to the controller.

Display units can be selected using either  $| \triangleleft |$  or  $| \triangleright |$ 

#### **Unit Display and Resolution**

Applicable pressure sensor		PSE530	PSE531	PSE532	PSE533
Regulating pressure range		–0.1 to 1 MPa	10 to –101 kPa	–10 to 101 kPa	–101 to 101 kPa
PA kPa MPa	—	0.1	0.1	0.1	
	MPa	0.001	_		_
kgf/cm <sup>2</sup>		0.01	0.001	0.001	0.001
bßr	bar	0.01	0.001	0.001	0.001
P5,	psi	0.1	0.01	0.01	0.02
Nnn	mmHg	_	1	_	1
, uy	inHg	—	0.1		0.1



 <sup>2</sup>ISE3

 PS

 <sup>2</sup>ISE1

 ZSP

 ISA2

 ISC

 ZSM

 PF2

 IF


 Data

ZSE□ ISE□


PSE

#### **Operation 4: Other Functions**

#### Reset




#### **Key lock**




Note) Channel selection and channel scan operation will not be locked even if the key lock function is on.

#### Peak/Bottom display



\* If any buttons other than above are pressed during the peak/bottom mode, the peak/bottom mode will be deactivated.

#### **Channel scan**



\* Pressure value for each channel are displayed at 2 second intervals.

**SMC** 

**Specific Product Precautions 1** 


Be sure to read before handling.

#### Pressure Sensor


#### Handling

# **∕**Marning

- 1. Do not drop, bump, or apply excessive impacts (980  $m/s^2$ ) while handling. Although the body of the sensor may not be damaged, the inside of the sensor could be damaged and lead to a malfunction.
- 2. The tensile strength of the cord is 23 N. Applying a greater pulling force on it can cause a malfunction. When handling, hold the body of the sensor—do not dangle it from the cord.
- 3. Do not exceed the screw-in torque of 3.5 N·m when installing piping. Exceeding this value may cause malfunctioning of the sensor.
- 4. Do not use pressure sensors with corrosive and/or inflammable gases or liquids.
- 5. Connecting the sensor cable (Option) Hold the female connector of the sensor cable with your fingers and carefully insert it into the connector.



A connector cover is provided as part of the cable assembly (see the figure below). It is designed to keep the female connector from slipping out of the sensor. To lock the connector cover in place, first make sure it is facing in the right direction as you slip it over the female connector, then lock it to the sensor body by turning it clockwise. To remove the cover, first unlock it by turning it counterclockwise, then pull back on it. To remove the female connector, grab it with your fingers and pull back on it. Do not pull on the cable.



#### **Operating Environment**

# **A**Warning

- 1. The pressure sensors are CE marked; however, they are not equipped with surge protection against lightning. Lightning surge countermeasures should be applied directly to system components as necessary.
- 2. The pressure sensors do not have an explosion proof rating. Never use pressure sensors in the presence of inflammable or explosive gases.

#### Controller

#### Handling

#### A Warning

- 1. Do not drop, bump, or apply excessive impacts (1000 m/s<sup>2</sup>) while handling. Although the body of the controller case may not be damaged, the inside of the controller could be damaged and cause a malfunction.
- 2. The tensile strength of the power supply/output connection cable is 50 N; that of the pressure sensor lead wire with connector is 25 N. Applying a greater pulling force than the applicable specified tensile strength to either of these components can lead to a malfunction. When handling, hold the body of the controller—do not dangle it from the cord.

#### Connection

#### 

- 1. Incorrect wiring can damage the switch and cause a malfunction or erroneous switch output. Connections should be done while the power is turned off.
- 2. Do not attempt to insert or pull the pressure sensor or its connector when the power is on. Switch output may malfunction.
- 3. Wire separately from power lines and high voltage lines, avoiding wiring in the same conduit with these lines. Malfunctions may occur due to noise from these other lines.
- 4. If a commercial switching regulator is used, make sure that the F.G. terminal is grounded.

#### **Operating Environment**

# **∕∆Warning**

- 1. Our multi-channel pressure sensor controllers are CE marked; however, they are not equipped with surge protection against lightning. Lightning surge countermeasures should be applied directly to system components as necessary.
- 2. Our multi-channel pressure sensor controllers do not have an explosion proof rating. Never use pressure sensors in the presence of inflammable or explosive gases.
- 3. Enclosure "IP65" applies only to the front face of the panel when mounting. Do not use in an environment where oil splashing or spraying are anticipated.

ZSE ISE ZSE3 PS ZSP ZSP ISA2 IS ZSM PF2 IF Data

**Specific Product Precautions 2** 


Be sure to read before handling.

#### Mounting

# **≜**Caution


The front face of the panel mount conforms to IP65 (IP40 when using the  $\Box$ 48 conversion adapter); however, there is a possibility of liquid filtration if the panel mount adapter is not installed securely and properly. Securely fix the adaptor with screws as shown below.

#### Standard



Tighten screws 1/4 to 1/2 turn after the heads are flush with the panel.

#### When using 248 conversion adapter



#### Wiring

#### **Caution** 1. Connecting sensor cable and connector (ZS-26-E)

- Cut the sensor cable as shown below.
- Insert each lead wire into the corresponding connector number by following the chart provided below.


Connector no.	Core wire color of sensor cable	20 mm or more
1	Brown (DC+)	
2	Black (Analog output)	
3	Blue (DC–)	Black 2 Blue 3
4	N.C.	N.C. 4

- Make sure that the number of connector and the core wire color match. After verifying that the wires are inserted all the way, temporarily hold the connector down manually.
- Using pliers, snap A into B as shown below so that there is no gap between A and B, and secure the connector.
- The A and B portion of the sensor connector are already tacked down temporarily at the time of shipment. Do not snap the A portion in place before inserting the cable. Note that the connector cannot be taken apart to be reused once it is crimped. Use a new sensor connector in case wiring or the snapping of A into B are done incorrectly.




Verify from the top side of A that the lead wires are inserted completely.

- To connect the connector to the multi-channel pressure sensor, push the connector with its A portion facing toward you into the socket until it clicks as shown below.
- To remove the connector, pull it straight out while applying pressure to the fingers on both sides.



#### 2. Connecting power supply/output connection cable

• To connect the power supply/output connection cable to the controller, insert the cable connector with the C part facing down until it clicks.



**Specific Product Precautions 3** 

Be sure to read before handling.

#### Wiring


# ▲Caution

#### 3. Connecting to other series

- Any pressure sensor (SW) can be connected as long as it generates analog output (1 to 5 V) signal. However, the pressure range must match.
- SMC pressure sensors, Series PSE510 & PSE520, are also connectable.
- When connecting to pressure sensors other than the Series PSE530, connector types will vary depending on the wire core size of the cable and the outside diameter of the insulation cover. Refer to the table provided below.

Connector part no.	Wire core size	Insulation cover O.D.	Sensor part no.
ZS-26-E	AWG24-26 (0.14 to 0.2 mm <sup>2</sup> )	ø1.0 to 1.4	PSE510, PSE530
ZS-26-E-1	AWG24-26 (0.14 to 0.2 mm <sup>2</sup> )	ø1.4 to 2.0	
ZS-26-E-2	AWG20-22 (0.3 to 0.5 mm <sup>2</sup> )	ø1.0 to 1.4	PSE521
ZS-26-E-3	AWG20-22 (0.3 to 0.5 mm <sup>2</sup> )	ø1.4 to 2.0	PSE520

• Refer to the following diagram for connecting Series PSE520 to the connector.



#### Regulating Pressure Range & Rated Pressure Range


# Caution

- 1. Regulating pressure range: Refers to allowable pressure range in a pressure setting mode.
- Setting range is between  $P_1(n_1)$  to  $P_4(n_4)$ .
- For Series PSE200, the regulating pressure range and the setting pressure range that can be displayed are the same.
- 2. Rated pressure range: Refers to the pressure range that satisfies the product specifications.
- Pressure range that satisfies the product specifications (accuracy and linearity) for PSE530.

ZSE□ ISE□
PSE
<sup>z</sup> SE3
PS
${}^{\mathbf{Z}}_{\mathbf{I}}\mathbf{SE}_{2}^{1}$
ZSP
ISA2
IS□
ZSM
PF2□
IF□
Data

# Safety Instructions

These safety instructions are intended to prevent a hazardous situation and/or equipment damage. These instructions indicate the level of potential hazard by labels of **"Caution", "Warning"** or **"Danger"**. To ensure safety, be sure to observe ISO 4414 <sup>Note 1)</sup>, JIS B 8370 <sup>Note 2)</sup> and other safety practices.



Note 2) JIS B 8370: General Rules for Pneumatic Equipment

# **A**Warning

1. The compatibility of pneumatic equipment is the responsibility of the person who designs the pneumatic system or decides its specifications.

Since the products specified here are used in various operating conditions, their compatibility for the specific pneumatic system must be based on specifications or after analysis and/or tests to meet your specific requirements. The expected performance and safety assurance will be the responsibility of the person who has determined the compatibility of the system. This person should continuously review the suitability of all items specified, referring to the latest catalog information with a view to giving due consideration to any possibility of equipment failure when configuring a system.

2. Only trained personnel should operate pneumatically operated machinery and equipment.

Compressed air can be dangerous if an operator is unfamiliar with it. Assembly, handling or repair of pneumatic systems should be performed by trained and experienced operators.

- 3. Do not service machinery/equipment or attempt to remove components until safety is confirmed.
  - 1. Inspection and maintenance of machinery/equipment should only be performed once measures to prevent falling or runaway of the driver objects have been confirmed.
  - 2. When equipment is to be removed, confirm the safety process as mentioned above. Cut the supply pressure for this equipment and exhaust all residual compressed air in the system.
  - 3. Before machinery/equipment is restarted, take measures to prevent shooting-out of cylinder piston rod, etc.

#### 4. Contact SMC if the product is to be used in any of the following conditions:

- 1. Conditions and environments beyond the given specifications, or if product is used outdoors.
- 2. Installation on equipment in conjunction with atomic energy, railway, air navigation, vehicles, medical equipment, food and beverages, recreation equipment, emergency stop circuits, clutch and brake circuits in press applications, or safety equipment.
- 3. An application which has the possibility of having negative effects on people, property, or animals, requiring special safety analysis.



# **Common Precautions**

Be sure to read before handling.

For detailed precautions on every series, refer to main text.

#### Selection

# \land Warning

#### 1. Confirm the specifications.

Products represented in this catalog are designed for use in compressed air appllications only (including vacuum), unless otherwise indicated.

Do not use the product outside their design parameters. Please contact SMC when using the products in applications other than compressed air (including vacuum).

#### Mounting

# A Warning

#### 1. Instruction manual

Install the products and operate them only after reading the instruction manual carefully and understanding its contents. Also keep the manual where it can be referred to as necessary.

#### 2. Securing the space for maintenance

When installing the products, please allow access for maintenance.

#### 3. Tightening torque

When installing the products, please follow the listed torque specifications.

#### Piping

# **▲** Caution

#### 1. Before piping

Make sure that all debris, cutting oil, dust, etc, are removed from the piping.

#### 2. Wrapping of pipe tape

When screwing piping or fittings into ports, ensure that chips from the pipe threads or sealing material do not get inside the piping. Also, when the pipe tape is used, leave 1.5 to 2 thread ridges exposed at the end of the threads.

#### Air Supply

# A Warning

#### 1. Operating fluid

Please consult with SMC when using the product in applications other than compressed air (including vacuum). Regarding products for general fluid, please ask SMC about applicable fluids.

#### 2. Install an air dryer, aftercooler, etc.

Excessive condensate in a compressed air system may cause valves and other pneumatic equipment to malfunction. Installation of an air dryer, after cooler etc. is recommended.

#### 3. Drain flushing

If condensate in the drain bowl is not emptied on a regular basis, the bowl will over flow and allow the condensate to enter the compressed air lines.

If the drain bowl is difficult to check and remove, it is recommended that a drain bowl with the auto-drain option be installed.

For compressed air quality, refer to "Air Preparation Equipment" catalog.

#### 4. Use clean air

If the compressed air supply is contaminated with chemicals, cynthetic materials, corrosive gas, etc., it may lead to break down or malfunction.

#### **Operating Environment**

#### 🗥 Warning

- 1. Do not use in environments where the product is directly exposed to corrosive gases, chemicals, salt water, water or steam.
- 2. Do not expose the product to direct sunlight for an extended period of time.
- 3. Do not use in a place subject to heavy vibrations and/or shocks.
- 4. Do not mount the product in locations where it is exposed to radiant heat.

#### Maintenance

#### 🗥 Warning

# 1. Maintenance procedures are outlined in the operation manual.

Not following proper procedures could cause the product to malfunction and could lead to damage to the equipment or machine.

#### 2. Maintenance work

If handled improperly, compressed air can be dangerous. Assembly, handling and repair of pneumatic systems should be performed by qualified personnel only.

#### 3. Drain flushing

Remove drainage from air filters regularly. (Refer to the specifications.)

#### 4. Shut-down before maintenance

Before attempting any kind of maintenance make sure the supply pressure is shut of and all residual air pressure is released from the system to be worked on.

5. Start-up after maintenance and inspection

Apply operating pressure and power to the equipment and check for proper operation and possible air leaks. If operation is abnormal, please verify product set-up parameters.


6. Do not make any modifications to be product. Do not take the product apart.



# Quality Assurance Information (ISO 9001, ISO 14001)

# Reliable quality of products in the global market

To enable our customers throughout the world to use our products with even greater confidence, SMC has obtained certification for international standards "ISO 9001" and "ISO 14001", and created a complete structure for quality assurance and environmental controls. SMC products to its pursue meet customers' expectations while also considering company's contribution in society.



SMC's quality control system

**Quality control activities** 

# Quality management system ISO 9001

This is an international standard for quality control and quality assurance. SMC has obtained a large number of certifications in Japan and overseas, providing assurance to our customers throughout the world.



# Environmental management system ISO 14001

This is an international standard related to environmental management systems and environmental inspections. While promoting environmentally friendly automation technology, SMC is also making diligent efforts to preserve the environment.



# SMC Product Conforming to Inter

SMC products complying with EN/ISO, CSA/UL standards are supporting



The CE mark indicates that machines and components meet essential requirements of all the EC Directives applied.

It has been obligatory to apply CE marks indicating conformity with EC Directives when machines and components are exported to the member Nations of the EU.

Once "A manufacturer himself" declares a product to be safe by means of CE marking (declaration of conformity by manufacturer), free distribution inside the member Nations of the EU is permissible.

#### ■ CE Mark

SMC provides CE marking to products to which EMC and Low Voltage Directives have been applied, in accordance with CETOP (European hydraulics and pneumatics committee) guide lines.

#### ■ As of February 1998, the following 18 countries will be obliged to conform to CE mark legislation

Iceland, Ireland, United Kingdom, Italy, Austria, Netherlands, Greece, Liechtenstein, Sweden, Spain, Denmark, Germany, Norway, Finland, France, Belgium, Portugal, Luxembourg

#### EC Directives and Pneumatic Components

#### • Machinery Directive

The Machinery Directive contains essential health and safety requirements for machinery, as applied to industrial machines e.g. machine tools, injection molding machines and automatic machines. Pneumatic equipment is not specified in Machinery Directive. However, the use of SMC products that are certified as conforming to EN Standards, allows customers to simplify preparation work of the Technical Construction File required for a Declaration of Conformity.

#### • Electromagnetic Compatibility (EMC) Directive

The EMC Directive specifies electromagnetic compatibility. Equipment which may generate electromagnetic interference or whose function may be compromised by electromagnetic interference is required to be immune to electromagnetic affects (EMS/immunity) without emitting excessive electromagnetic affects (EMI/emission).

#### Low Voltage Directive

This directive is applied to products, which operate above 50 VAC to 1000 VAC and 75 VDC to 1500 VDC operating voltage, and require electrical safety measures to be introduced.

#### • Simple Pressure Vessels Directive

This directive is applied to welded vessels whose maximum operating pressure (PS) and volume of vessel (V) exceed 50 bar/L. Such vessels require EC type examination and then CE marking.



# national Standards

you to comply with EC directives and CSA/UL standards.



#### CSA Standards & UL Standards

UL and CSA standards have been applied in North America (U.S.A. and Canada) symbolizing safety of electric products, and are defined to mainly prevent danger from electric shock or fire, resulting from trouble with electric products. Both UL and CSA standards are acknowledged in North America as the first class certifying body. They have a long experience and ability for issuing product safety certificate. Products approved by CSA or UL standards are accepted in most states and governments beyond question.

Since CSA is a test certifying body as the National Recognized Testing Laboratory (NRTL) within the jurisdiction of Occupational Safety and Health Administration (OSHA), SMC was tested for compliance with CSA Standards and UL Standards at the same time and was approved for compliance with the two Standards. The above CSA NRTL/C logo is described on a product label in order to indicate that the product is approved by CSA and UL Standards.

#### ■ TSSA (MCCR) Registration Products

TSSA is the regulation in Ontario State, Canada. The products that the operating pressure is more than 5 psi (0.03 MPa) and the piping size is bigger than 1 inch. fall into the scope of TSSA regulation.


Products conforming to CE Standard

# With CE symbol for simple visual recognition

In this catalog each accredited product series is indicated with a CE mark symbol. However, in some cases, every available models may not meet CE compliance. Please visit our web site for the latest selection of available models with CE mark.

#### http://www.smcworld.com

# **SMC's Global Service Network**



#### America

U.S.A. SMC Corporation of America 3011 North Franklin Road Indianapolis, IN 46226, U.S.A. TEL: 317-899-4440 FAX: 317-899-3102

CANADA SMC Pneumatics (Canada) Ltd. 6768 Financial Drive Mississauga, Ontario, L5N 7J6 Canada TEL: 905-812-0400 FAX: 905-812-8686

MEXICO SMC Corporation (Mexico), S.A. DE C.V. Carr. Silao-Trejo K.M. 2.5 S/N, Predio San Jose del Duranzo C.P. 36100, Silao, Gto., Mexico TEL: 472-72-2-55-00 FAX: 472-72-2-59-44/2-59-46

CHILE SMC Pneumatics (Chile) S.A. Av. La Montaña 1,115 km. 16,5 P. Norte Parque Industrial Valle Grande, Lampa Santiago, Chile TEL: 02-270-8600 FAX: 02-270-8601

ARGENTINA SMC Argentina S.A. Teodoro Garcia 3860 (1427) Buenos Aires, Argentina TEL: 011-4555-5762 FAX: 011-4555-5762

BOLIVIA SMC Pneumatics Bolivia S.R.L. Avenida Beni Numero 4665 Santa Cruz de la Sierra-Casilla de Correo 2281, Bolivia TEL: 591-3-3428383 FAX: 591-3-3449900

VENEZUELA SMC Neumatica Venezuela S.A. Apartado 40152, Avenida Nueva Granada, Edificio Wanlac, Local 5, Caracas 1040-A, Venezuela TEL: 2-632-1310 FAX: 2-632-3871

PERU (Distributor) IMPECO Automatizacion Industrial S.A. AV. Canevaro 752, Lince, Lima, Peru TEL: 1-471-6002 FAX: 1-471-0935

URUGUAY (Distributor) BAKO S.A. Galicia 1650 esq. Gaboto C.P. 11200, Montevideo, Uruguay TEL: 2-401-6603 FAX: 2-409-4306

BRAZIL SMC Pneumaticos Do Brasil Ltda. Rua. Dra. Maria Fidelis, nr. 130, Jardim Piraporinha-Diadema-S.P. CEP: 09950-350, Brasil TEL: 11-4051-1177 FAX: 11-4071-6636

COLOMBIA (Distributor) Airmatic Ltda. Calle 18 69-05 Apart. Aereo 081045 Santa Fe de Bogotá, Colombia TEL: 1-424-9240 FAX: 1-424-9260

#### Europe

U.K. SMC Pneumatics (U.K.) Ltd. Vincent Avenue, Crownhill, Milton Keynes, MK8 0AN, Backinghamshire, U.K. TEL: 01908-563888 FAX: 01908-561185

GERMANY SMC Pneumatik GmbH Boschring 13-15 D-63329 Egelsbach, Germany TEL: 06103-4020 FAX: 06103-402139

ITALY SMC Italia S.p.A. Via Garibaldi 62 I-20061 Carugate Milano, Italy TEL: 02-9271365 FAX: 02-9271365

FRANCE SMC Pneumatique S.A. 1 Boulevard de Strasbourg, Parc Gustave Eiffel, Bussy Saint Georges, F-77600 Marne La Vallee Cedex 3 France TEL: 01-64-76-10-00 FAX: 01-64-76-10-10

SWEDEN SMC Pneumatics Sweden AB Ekhagsvägen 29-31, S-141 05 Huddinge, Sweden TEL: 08-603-07-00 FAX: 08-603-07-10

SWITZERLAND SMC Pneumatik AG Dorfstrasse 7, Postfach 117, CH-8484 Weisslingen, Switzerland TEL: 052-396-3131 FAX: 052-396-3191

AUSTRIA SMC Pneumatik GmbH (Austria) Girakstrasse 8, A-2100 Korneuburg, Austria TEL: 0-2262-6228-0 FAX: 0-2262-62285

SPAIN SMC España, S.A. Zuazobidea 14 Pol. Ind. Júndiz 01015 Vitoria, Spain TEL: 945-184-100 FAX: 945-184-510

IRELAND SMC Pneumatics (Ireland) Ltd. 2002 Citywest Business Campus, Naas Road, Saggart, Co. Dublin, Ireland TEL: 01-403-9000 FAX: 01-466-0385

NETHERLANDS (Associated company) SMC Pneumatics BV De Ruyterkade 120, NL-1011 AB Amsterdam, Netherlands TEL: 020-5318888 FAX: 020-5318880

GREECE (Distributor) **S.Parianopoulos S.A.** 7, Konstantinoupoleos Street 11855 Athens, Greece TEL: 01-3426076 FAX: 01-3455578

DENMARK SMC Pneumatik A/S Knudsminde 4 B DK-8300 Odder, Denmark TEL: 70252900 FAX: 70252901

**SMC** 

#### Europe

FINLAND SMC Pneumatics Finland OY PL72, Tiistinniityntie 4, SF-02231 ESP00, Finland TEL: 09-8595-80 FAX: 09-8595-8595

NORWAY SMC Pneumatics Norway A/S Vollsveien 13C, Granfoss Næringspark N-1366 LYSAKER, Norway TEL: 67-12-90-20 FAX: 67-12-90-21

BELGIUM (Distributor) SMC Pneumatics N.V./S.A. Nijverheidsstraat 20 B-2160 Wommelgem Belguim TEL: 03-355-1464 FAX: 03-355-1466

POLAND SMC Industrial Automation Polska Sp.z.o.o. ul. Konstruktorska 11A, PL-02-673 Warszawa, Poland TEL: 022-548-5085 FAX: 022-548-5087

TURKEY (Distributor) Entek Pnömatik San.ve Tic. Ltd. Sti Perpa Tic. Merkezi Kat:11 No.1625 80270 Okmeydani Istanbul, Türkiye TEL: 0212-221-1512 FAX: 0212-221-1519

RUSSIA SMC Pneumatik LLC. 36/40 Sredny prospect V.O. St. Petersburg 199004, Russia TEL: 812-118-5445 FAX: 812-118-5449

CZECH **SMC Industrial Automation CZ s.r.o.** Hudcova 78a, CZ-61200 Brno, Czech Republic TEL: 05-4121-8034 FAX: 05-4121-8034

HUNGARY SMC Hungary Ipari Automatizálási kft. Budafoki ut 107-113 1117 Budapest TEL: 01-371-1343 FAX: 01-371-1344

ROMANIA SMC Romania S.r.I. Str. Frunzei, Nr. 29, Sector 2, Bucharest, Romania TEL: 01-3205111 FAX: 01-3261489

SLOVAKIA SMC Priemyselná automatizáciá, s.r.o Nova 3, SK-83103 Bratislava TEL: 02-4445-6725 FAX: 02-4445-6028

SLOVENIA SMC Industrijska Avtomatilca d.o.o. Grajski trg 15, SLO- 8360 Zuzemberk, Slovenia TEL: 07388-5240 FAX: 07388-5249

LATVIA **SMC Pneumatics Latvia SIA** Šmerļa ielā 1-705, Rīga LV-1006 TEL: 777 94 74 FAX: 777 94 75

SOUTH AFRICA (Distributor) Hyflo Southern Africa (Pty.) Ltd. P.O.Box 240 Paardeneiland 7420 South Africa TEL: 021-511-7021 FAX: 021-511-4456

EGYPT (Distributor) Saadani Trading & Ind. Services 15 Sebaai Street, Miami 21411 Alexandria, Egypt TEL: 3-548-50-34 FAX: 3-548-50-34 Oceania/Asia

AUSTRALIA SMC Pneumatics (Australia) Pty.Ltd. 14-18 Hudson Avenue Castle Hill NSW 2154, Australia TEL: 02-9354-8222 FAX: 02-9894-5719

NEW ZEALAND SMC Pneumatics (New Zealand) Ltd. 8C Sylvia Park Road Mt.Wellington Auckland, New Zealand TEL: 09-573-7007 FAX: 09-573-7002

TAIWAN SMC Pneumatics (Taiwan) Co.,Ltd. 17, Lane 205, Nansan Rd., Sec.2, Luzhu-Hsiang, Taoyuan-Hsien, TAIWAN TEL: 03-322-3443 FAX: 03-322-3387

HONG KONG SMC Pneumatics (Hong Kong) Ltd. 29/F, Clifford Centre, 778-784 Cheung, Sha Wan Road, Lai Chi Kok, Kowloon, Hong Kong TEL: 2744-0121 FAX: 2785-1314

SINGAPORE SMC Pneumatics (S.E.A.) Pte. Ltd. 89 Tuas Avenue 1, Jurong Singapore 639520 TEL: 6861-0888 FAX: 6861-1889

PHILIPPINES SHOKETSU SMC Corporation Unit 201 Common Goal Tower, Madrigal Business Park, Ayala Alabang Muntinlupa, Philippines TEL: 02-8090565 FAX: 02-8090586

MALAYSIA SMC Pneumatics (S.E.A.) Sdn. Bhd. Lot 36 Jalan Delima1/1, Subang Hi-Tech Industrial Park, Batu 3 40000 Shah Alam Selangor, Malaysia TEL: 03-56350590 FAX: 03-56350602

SOUTH KOREA SMC Pneumatics Korea Co., Ltd. Woolim e-BIZ Center (Room 1008), 170-5, Guro-Dong, Guro-Gu, Seoul, 152-050, South Korea TEL: 02-3219-0700 FAX: 02-3219-0702

CHINA SMC (China) Co., Ltd. 7 Wan Yuan St. Beijing Economic & Technological Development Zone 100176, China TEL: 010-67882111 FAX: 010-67881837

THAILAND SMC Thailand Ltd. 134/6 Moo 5, Tiwanon Road, Bangkadi, Amphur Muang, Patumthani 12000, Thailand TEL: 02-963-7099 FAX: 02-501-2937

INDIA SMC Pneumatics (India) Pvt. Ltd. D-107 to 112, Phase-2, Extension, Noida, Dist. Gautaim Budh Nagar, U.P. 201 305, India TEL: (0120)-4568730 FAX: 0120-4568933

INDONESIA (Distributor) P.T. Riyadi Putera Makmur Jalan Hayam Wuruk Komplek Glodok Jaya No. 27-28 Jakarta 11180 Indonesia TEL: 021-625 5548 FAX: 021-625 5888

PAKISTAN (Distributor) Jubilee Corporation First Floor Mercantile Centre, Newton Road Near Boulton Market P.O. Box 6165 Karachi 74000 Pakistan TEL: 021-243-9070/8449 FAX: 021-241-4589

ISRAEL (Distributor) Baccara Automation Control Kvutzat Geva 18915 Israel TEL: 04-653-5960 FAX: 04-653-1445

SAUDI ARABIA (Distributor) Assaggaff Trading Est. P.O. Box 3385 Al-Amir Majed Street, Jeddah-21471, Saudi Arabia TEL: 02-6761574 FAX: 02-6708173