



Pt100 Input module

Identification		Part number	Male insert (M)	Drawing	Dimensions in mm
Temperature module	Pt100				
Measuring range	0 ... 100 °C	20 75 108 1101			
	0 ... 200 °C	20 75 108 1103			

Han
Modular