
## **M83 Datamate Connectors**

## Male Horizontal PC Tail




B + 15


(Total No. of contacts - 3) x 2/3


Α В


C


















Diagram shown with Jackscrew M5 assembled.

Recommended PC Board Pattern



18, 27, 36, 48, 54, 60, 96

JACKSCREW	
00	No Jackscrew
Mx	Male Jackscrews – see page 65

All dimensions in mm.

















