
Han® Q 5/0 Inserts with PCB adapter

230/400 V 10 A





Further informations see chapter 13 (Han[®] Q)